

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 07.08.2020

RE: VEHICLE REPAIR QUOTATION

Insurance Company

Vehicle Reg No

Name of Insured

Policy Number

Date of Accident

Tyre of Claim

Model

Chassis No

IKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AIG Asia Pacific Insurance P/L

SLZ1986U

07.08.2020

Third Party Claim

BMW 523I 2.5AT

WBAFP32060C865362

Not Authorized
 11 Lms @ 3800k
 Resurvey After Paint
 Kenneth Hong @ IKKauto.com
 3 days

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT BUMPER	Bu \$ 1,626.44	✓
2	TOW HOOK COVER	na \$ 154.64	✓
3	REINFORCEMENT UPPER	R \$ 795.93	X
4	SPONGE	su \$ 85.16	X
5	FRONT BUMPER LOWER GRILLE	na \$ 99.56	✓
6	FRONT BUMPER FOG LAMP	cm \$ 329.46	✓
7	FRONT HEADLAMP RH	wt \$ 2,585.78	✓
8	FRONT BUMPER GRILLE RH	cm \$ 189.66	✓
9	FRONT BUMPER GRILLE LH	su \$ 189.66	X
10	FRONT BUMPER LOGO	na \$ 139.63	✓

Sub Total Parts \$ 6,195.92

Less 5% \$ 309.80

Total Parts \$ 5,886.12

1	Sundries	\$ na 50.00	X
2	Wiring connection and check.	\$ 150.00	2cl
3	Tuff kote and spray anti rust proofing	\$ na 150.00	X
4	Labour charges to dismantle & refix front bumper front fog lamp cover, side retainer, chrome lower To repair and adjust affected portion to specific dimension.	\$ 500.00	30cl
5	To spray paint front bumper, front Rh fender and all other accident affected portion	\$ 500.00	40cl
6	Remove and replace front bumper sensor	\$ 150.00	6cl
7	To supply and install front bumper plate with holder	\$ na 55.00	X
7	To conduct ECU programming, check and clear fault codes, restore programme modules	\$ na 350.00	X
Total (Labour)		\$ 1,905.00	

ASS. REC. BY:

REF:

A/G/ 2000 8233/KK

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

10/9 21 Sup & 38od Carbur

Veh No:

SL 7 19864

Yr Regn:

04 11

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

BMW

503i

c.c

2497

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

148632

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP 3 2000 C 865362

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

TOYO 245/40ZR19

R:

Miz 275/35ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

1

mm

R/Bal.

2

mm

L/Bal.

1

mm

L/Bal.

2

mm

D.O.A.

3/8/20

D.O.I.

12/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

FURTHER

OTHERS

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$