

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG20008240/R1QF3E2**Date:** 10/11/2020**REFERENCE**

Insured/Claimant:	DUMIR NEERAJ	Policy No:	1800114782
Date of Loss:	08/08/2020	Nature of Claim:	OD
		Claim No:	3638277090SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME2867Y</b>		
Make & Model:	AUDI A4, 2.0 TFSI Limited Edition (A)	Engine No:	CVK069008
Reg. Date:	25/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF49JA232987
Colour:	Blue	Odometer:	9760 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$139,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	29,186.40	15,979.36	13,207.04	45.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,664.00	7,414.00	4,250.00	36.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>40,850.40</b>	<b>23,393.36</b>	<b>17,457.04</b>	<b>42.73</b>
<b>- Excess (\$\$)</b>	1,600.00	1,600.00	0.00	0.00
<b>(\$\$)</b>	39,250.40	21,793.36	17,457.04	44.48
<b>+ GST 7.00/7.00% (\$\$)</b>	2,747.53	1,525.54	1,221.99	44.48
<b>Nett Amount (\$\$)</b>	<b>41,997.93</b>	<b>23,318.90</b>	<b>18,679.03</b>	<b>44.48</b>

**INSPECTION**

Date of Assignment:	11/08/2020	
Date Inspected:	12/08/2020	Inspected At: 24 Benoi Sector
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,171.00 FS	*1,736.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	282.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Serviceable	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Serviceable	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	208.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Serviceable	62.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,317.00 FS	*1,053.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Serviceable	134.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Bent	795.00 FS	*635.60 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	123.00 FS	*98.40 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE COVER	Serviceable	126.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	36.00 FS	*28.48 FS
13	1		*FRONT BUMPER BRACKET - LH/RH	N/S Cracked / O/S Serviceable	225.00 FS	*180.00 FS
14	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
15	1		*LOCK CARRIER STICKER	Cracked	136.00 FS	*108.40 FS
16	2		*FRONT BUMPER SUPPORT - LH/RH	Necessary	56.00 FS	*44.48 FS
17	1		*FRONT PARKING AID SENSOR - INNER/OUTER (2PCS)	Not Working (1Pc Only)	386.40 FS	*193.20 FS
18	1		*FRONT BUMPER WIRING SET	Not Necessary	505.00 FS	*- FS
19	1		*HORN - LH HIGH TONE	Not Necessary	124.00 FS	*- FS
20	1		*SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
21	1		*FRONT FENDER - LH/RH	N/S Bent / O/S NotNecessary	758.00 FS	*606.00 FS
22	1		*FRONT FENDER ATTACHMENTS PARTS	Serviceable	200.00 FS	*- FS
23	1		*FRONT FENDER CLOSING ELEMENT - LH	Cracked	49.00 FS	*39.20 FS
24	1		*FRONT FENDER BRACKET - LH	Bent	35.00 FS	*27.60 FS
25	1		*DEFORMATION ELEMENT BRACKET - LH	Serviceable	49.00 FS	*- FS
26	1		*FRONT FENDER BRACKET	Serviceable	31.00 FS	*- FS
27	1		*FRONT FENDER BRACE - LH	Bent	117.00 FS	*93.60 FS
28	1		*TOP FENDER LEDGE COVER - LH UPPER	Necessary	31.00 FS	*24.40 FS
29	1		*TOP FENDER LEDGE COVER - LH LOWER	Necessary	23.00 FS	*17.68 FS
30	1		*WHEEL HOUSING LINER - LH	Serviceable	237.00 FS	*- FS
31	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
32	1		*WHEEL SPOILER	Serviceable	73.00 FS	*- FS
33	1		*WHEEL SPOILER TRIM - LH	Serviceable	35.00 FS	*- FS
34	1		*STONE CHIP GUARD - LH	Necessary	50.00 FS	*39.92 FS
35	1		*BONNET	Bent	2,763.00 FS	*2,210.40 FS
36	1		*BONNET ATTACHMENT PARTS	Serviceable	121.00 FS	*- FS
37	2		*BONNET LID HINGE - LH/RH	Serviceable	602.00 FS	*- FS
38	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	27.00 FS	*21.52 FS
39	1		*BONNET IMPACT PROTECTION - RH	Necessary	27.00 FS	*21.52 FS
40	1		*BONNET IMPACT PROTECTION - LH	Necessary	28.00 FS	*21.84 FS
41	2		*BONNET STRIKER - LH/RH	Serviceable	100.00 FS	*- FS
42	1		*BONNET LID LOCK	N/S Bent / O/S Serviceable	423.00 FS	*169.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BONNET BOWDEN CABLE - CENTRE	Serviceable	57.00 FS	*- FS
44	1		*BONNET BOWDEN CABLE	Serviceable	57.00 FS	*- FS
45	1		*BONNET RELEASE LEVER	Serviceable	13.00 FS	*- FS
46	1		*BONNET SOUND ABSORBER	Serviceable	339.00 FS	*- FS
47	1		*LED HEADLIGHT - LH	Broken	7,693.00 FS	*6,154.40 FS
48	1		*MAIL LIGHT ELECTRONICS POWER MODULE	Cracked	739.00 FS	*591.20 FS
49	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Cracked	742.00 FS	*593.60 FS
50	2		*HEADLIGHT HOSE - LH/RH	Serviceable	36.00 FS	*- FS
51	1		*HEADLIGHT REPAIR KIT - LH	Serviceable	130.00 FS	*- FS
52	1		*HEADLIGHT COMPENSATING PIECE	Serviceable	40.00 FS	*- FS
53	1		*HEADLIGHT COMPENSATING PIECE	Serviceable	40.00 FS	*- FS
54	1		*HEADLIGHT COMPENSATING PIECE	Serviceable	40.00 FS	*- FS
55	1		*LIFT CYLINDER - LH	Cracked	208.00 FS	*166.00 FS
56	1		*LIFT CYLINDER CORRUGATED PIPE	Serviceable	92.00 FS	*- FS
57	1		*LOCK CARRIER	Bent	1,004.00 FS	*803.20 FS
58	1		*LOCK CARRIER SUPPORT	Serviceable	38.00 FS	*- FS
59	1		*AIRCON CONDENSER	Serviceable	615.00 FS	*- FS
60	1		*REFRIGERANT LINE	Serviceable	165.00 FS	*- FS
61	1		*REFRIGERANT LINE	Serviceable	336.00 FS	*- FS
62	1		*TEMPERATURE SENSOR BRACKET	Necessary	18.00 FS	*14.40 FS
63	1		*PRESSURE PIPE	Serviceable	422.00 FS	*- FS
64	1		*RADIATOR	Not Necessary	837.00 FS	*- FS
65	1		*READY MIX COOLANT	Necessary	91.00 FS	*72.32 FS
66	1		*RADIATOR FAN RING	Not Necessary	242.00 FS	*- FS
67	1		*RADIATOR FAN	Not Necessary	1,896.00 FS	*- FS
68	1		*RADIATOR AIR GUIDE - LH	Not Necessary	28.00 FS	*- FS
69	1		*RADIATOR AIR GUIDE - LH	Deformed	12.00 FS	*9.36 FS
70	1		*RADIATOR AIR GUIDE - UPPER	Serviceable	16.00 FS	*- FS
71	1		*FRONT NO. PLATE	Necessary	60.00 FS	*60.00 FS
72	1		*SUNDRIES	Necessary	300.00 FS	*132.24 FS
73	1		*LIFT CYLINDER BRACKET LHS	Not Necessary	6.00 FS	*- FS
74	1		*RADIATOR OUTER AIR GUIDE RHS	Not Necessary	12.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **29,186.40** **15,979.36**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER/ REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM.	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	350.00	250.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	New	350.00	350.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLERS AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,200.00	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,900.00	2,750.00
6	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, HINGES AND LHS FRONT DOOR.	New	4,200.00	2,200.00
7	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	New	384.00	384.00
<b>Gross Labour Cost (S\$)</b>			<b>11,664.00</b>	<b>7,414.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >