

ASS. REC. BY:

REF:

FC2/20008244/KK

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 118K

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 08 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNK 8368EYr Regn: 07, 19Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyc.c. 2487Colour: M. Silver

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 109460

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AXV1470

1032199

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / RIM or

Tyre Size: F: _____

R: _____

215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 8/8/20D.O.A. 11/8/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/8 21 Rm 889501 Confirms

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format: _____

Lump Sum / I.B.I: (\$)

First copy

辉 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

08/08/2020

Owner: MOHAMAD AZELI BIN AHWAN

Not Authorized
 11 Lm @ 8950/2
 Recovery After Pain
 8 days

ESTIMATE TO REPAIR TOYOTA CAMRY 2.5A - SMK8366E

1pc	front LH fender	\$ 781.50	X
1pc	front LH fender "HYBRID"	\$ 85.25	✓
1pc	front LH side windscreen pillar	\$ 681.50	X
1set	front windscreen moulding	\$ 195.58	X
1pc	front LH side mirror	\$ 681.52	✓
1pc	front LH side mirror cover	\$ 181.50	✓
1pc	front LH door 1658	\$ 1,781.50	✓
1pc	front LH door handle (chrome)	\$ 381.50	✓
1pc	front LH door handle base	\$ 358.20	X
1pc	front LH door moulding (chrome)	\$ 381.25	✓
1pc	front LH door frame top moulding (chrome)	\$ 358.25	✓
12pcs	front LH door frame top moulding rivet @\$8.00	\$ 96.00	✓
1pc	front LH door garnish	\$ 195.50	✓
1pc	front LH door glass	\$ 981.25	✓
1pc	front LH door panel (tirm) 1428	\$ 1,850.25	✓
1pc	front LH door inner rudder	\$ 281.50	✓
2pcs	front LH door inner frame sticker @\$171.25	\$ 342.50	✓
1pc	rear LH door 1550	\$ 1,681.50	✓
1pc	rear LH door moulding (chrome)	\$ 381.25	✓
12pcs	rear LH door frame top moulding rivet @\$8.00	\$ 96.00	✓
1pc	rear LH door inner frame sticker @\$171.25	\$ 342.50	✓
1pc	rear LH door handle (chrome)	\$ 381.50	✓
1pc	rear LH door handle base	\$ 358.25	X
1pc	rear LH fender 1178.10	\$ 1,285.50	✓
1set	rear windscreen moulding	\$ 191.50	✓
		\$ 14,332.55	
less 25%		\$ 3,583.14	
		\$ 10,749.41	

1set	door visor	Pr?
1pc	front LH door glass soler film	
	windscreen sealant	

CMA	s.nett	\$ 380.00	18052
nu	s.nett	\$ 160.00	10052
nu	s.nett	\$ 180.00	4052

Balance c/f

\$ 11,469.41



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

08/08/2020

Owner: MOHAMAD AZELI BIN AHWAN

ESTIMATE TO REPAIR TOYOTA CAMRY 2.5A - SMK8366E

Balance b/f \$ 15,052.55

remove & refit front & rear windscreen glass	\$ 240.00	1200
remove & refit LH front & rear door glass	\$ 160.00	1200
tuffkote	\$ 280.00	900
wiring	\$ 250.00	400
spray painting	\$ 1,800.00	11500
labour charges	\$ 1,800.00	10000
Total	\$ 19,582.55	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

