

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20008254/AQF3E2

Date: 16/09/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMPG19011648

Claimant Vehicle No : PC5354R **Insured Vehicle No :** SJZ4956K

Date of Loss: 07/08/2020 Nature of Claim: TP Claim No: CDMPG20001064

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC5354R**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 4DR (A) Engine No: 1KD2656838
 Reg. Date: 20/01/2017 (Man. Year: 2016) Chassis No: JTFHT02P900207885
 Colour: White Odometer: 87661 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,052.65	4,979.81	11,072.84	68.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	2,310.00	1,130.00	32.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,492.65	7,289.81	12,202.84	62.60
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	19,492.65	5,800.00	13,692.65	70.25
+ GST 7.00/7.00% (S\$)	1,364.49	406.00	958.49	70.25
Nett Amount (S\$)	20,857.14	6,206.00	14,651.14	70.25

INSPECTION

Date of Assignment: 11/08/2020

Date Inspected: 11/08/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Sep 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5354R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,712.45 F	*1,712.45 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	343.40 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	748.90 F	*- FL
4	1		*REAR BOOT LID TOYOTA HIACE STICKER	Necessary	57.60 F	*57.60 FL
5	1		*REAR BOOT LID EMERGENCY STICKER	Necessary	50.00 FS	*20.00 FS
6	1		*REAR BOOT ID CUSTOMED STICKER	Necessary	50.00 FS	*20.00 FS
7	1		*REAR BOOT LID EMBLEM LOGO	Necessary	41.10 F	*41.10 FL
8	1		*REAR BOOT LID CENTRE MOULDING	Not Necessary	281.90 F	*- FL
9	1		*REAR BOOT LID INNER LOCK	Damaged	374.25 F	*374.25 FL
10	1		*REAR BOOT LID INNER POWER LOCK	Not Necessary	276.20 F	*- FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	381.90 F	*381.90 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Torn	581.10 F	*165.30 FL
13	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	65.00 F	*30.00 FL
14	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
15	1		*REAR L/H TAIL LAMP	Cracked	371.45 F	*371.45 FL
16	1		*REAR L/H TAIL LAMP PANEL	Dented	355.80 F	*355.80 FL
17	1		*REAR L/H TAIL LAMP LOWER COVER	Deformed	182.10 F	*182.10 FL
18	1		*REAR L/H TAIL LAMP LOWER COVER RETAINER	Not Necessary	171.45 F	*- FL
19	2		*REAR L/H TAIL LAMP CLIP	Necessary	16.00 F	*16.00 FL
20	1		*REAR L/H FENDER	Repair	1,989.90 F	*- FL
21	1		*REAR L/H FENDER ADVERTISEMENT STICKER	Necessary	550.00 FS	*200.00 FS
22	1		*REAR L/H FENDER AIR DUCT	Deformed	172.45 F	*172.45 FL
23	2		*REAR L/H FENDER GLASS SEAL	Not Necessary	100.00 F	*- FL
24	1		*REAR L/H FENDER INNER PANEL	Repair	631.35 F	*- FL
25	1		*REAR BUMPER	Distorted	374.45 F	*374.45 FL
26	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
27	1		*REAR L/H BUMPER SIDE RETAINER	Necessary	131.35 F	*131.35 FL
28	1		*REAR END PANEL OUTER	Dented	581.10 F	*581.10 FL
29	1		*REAR END PANEL INNER	Dented	591.25 F	*591.25 FL
30	8		*REAR END PANEL TOP CLIP	Not Necessary	52.00 F	*- FL
31	1		*REAR FLOOR PANEL	Repair	1,850.00 F	*- FL
32	1		*REAR FLOOR PANEL TOP MOULDING	Bent	174.10 F	*174.10 FL
33	8		*REAR FLOOR PANEL TOP MOULDING CLIP	Necessary	52.00 F	*20.00 FL
34	1		*REAR FLOOR PANEL CARPET	Not Necessary	850.00 FS	*- FS
35	1		*REAR FLOOR PANEL PLYWOOD	Not Necessary	450.00 FS	*- FS
36	1		*REAR SPARE TYRE BRACKET	Bent	172.10 F	*172.10 FL
37	1		*REAR BOOT LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
38	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 FS	*- FS
39	1		*REAR BOOT LID CAMERA	Not Necessary	680.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	16,052.65
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00
					Total Parts (\$\$)	16,052.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE & REFIT L/H FENDER GLASS	New	120.00	0.00
4	GUM	New	50.00	50.00
5	TO CHECK WIRING	New	100.00	30.00
6	TUFF KOTE	New	150.00	60.00
7	PANEL BEATING	New	1,400.00	1,000.00
8	SPRAY PAINTING	New	1,400.00	1,000.00
Gross Labour Cost (S\$)			3,440.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >