

## Accident Repair Estimate

|                           |                        |                         |           |
|---------------------------|------------------------|-------------------------|-----------|
| ACCIDENT DATE             | 28.07.2020             | BUS REGISTRATION NUMBER | SBS 3198U |
| ACCIDENT TIME             | 11:35 HRS              | BUS TYPE (DD OR SD)     | DD        |
| THIRD PARTY CLAIM AGAINST | TOWING TRUCK, XE 5058R |                         |           |

### SECTION A :

### PARTS & MATERIAL COST

| Part or Item Description                                                        | Quantity | Total Cost         |
|---------------------------------------------------------------------------------|----------|--------------------|
| O/S LOWER ENG ACCESS; SHEET METAL - 30 750 059 <i>bt /</i>                      | 1        | \$ 1,620.35        |
| SIDE SHEET METAL PANEL - 30 750 041 <i>bt /</i>                                 | 1        | \$ 190.78          |
| SIDE SHEET METAL PANEL - 30 750 042 <i>bt /</i>                                 | 1        | \$ 769.32          |
| SIDE SHEET METAL PANEL - 30 750 060 <i>bt /</i>                                 | 1        | \$ 853.46          |
| GLASS.SIDE.4MM.GLAZING - 30 750 007 <i>bro /</i>                                | 2        | \$ 500.00          |
| GLASS.SIDE.4MM.GLAZING. O/N/S - 30 117 229 <i>bro /</i>                         | 1        | \$ 153.96          |
| WINDOW RBBR;N/S;O/S BODY;12MM - 30 117 030 <i>sc /</i>                          | 1        | \$ 85.00           |
| TECHNA 6 WAY SWITCH PANEL-VM6 - 30 750 407 <i>bt /</i>                          | 1        | \$ 36.01           |
| ALLOY CAPPING FOR LOWER DECK SIDE PLANK - 30 750 383 <i>bt /</i>                | 1        | \$ 84.00           |
| SEALED LEVER LATCH;OS/NS;RR SIDE DR - 30 750 003 <i>sm /</i>                    | 2        | \$ 68.60           |
| <i>(centre)</i> FRT OS CORNER DEFLECTOR COMP MOULD CL2 - 30 750 000 <i>nc /</i> | 2        | \$ 118.00          |
| BOSTICK SEALANT 7008 - 30 730 009 <i>nc /</i>                                   | 7        | \$ 108.50          |
| LAST ITEM                                                                       | -        | \$ -               |
|                                                                                 |          | \$ -               |
|                                                                                 |          | \$ -               |
|                                                                                 |          | \$ -               |
| <b>TOTAL PARTS &amp; MATERIAL COST</b>                                          |          | <b>\$ 4,587.98</b> |

### SECTION B:

### ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)

|                          |                    |
|--------------------------|--------------------|
| Labour                   | \$ 5,700.00        |
| Spray Painting           | \$ 2,750.00        |
|                          |                    |
| <b>TOTAL LABOUR COST</b> | <b>\$ 8,450.00</b> |

### SECTION C :

### SUMMARY

|                           |                     |
|---------------------------|---------------------|
|                           |                     |
| <b>TOTAL REPAIR COSTS</b> | <b>\$ 13,037.98</b> |
| <b>TOTAL DOWNTIME</b>     | <b>8.0 days</b>     |

18,169.84#