

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jul 2020		12 Aug 2020 10:56 Edit Adj Rpt	S\$17,569.84 Edit Estimates	S\$17,569.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SINGAPORE TOWING PTE LTD , Co. Reg. No.: 201721244E									
Main Claimant: SBS TRANSIT LTD , Co. Reg. No.: 199206653M									
Vehicle Reg. No.: SBS3198U		Date of Loss: 28/07/2020 12:00 - :59 [94 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D202643/C02/THAMYL		Policy/Cover Note No.: DMCVSNW00056942001							
Vehicle Reg. No. (Insured): XE5058R		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: SBS Transit Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/08/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBS3198U (SNM20D202643/C02/THAMYL)
[XE5058R]**

TP

**SBS TRANSIT LTD
Jul 28 2020 12:00PM
[SINGAPORE TOWING PTE LTD]
SBS Transit Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/20 21:28	Chassis Number	 Load JPG	
2	16/08/20 21:28	General View	 Load JPG	
3	16/08/20 21:28	General View	 Load JPG	
4	16/08/20 21:28	General View	 Load JPG	
5	16/08/20 21:28	General View	 Load JPG	
6	16/08/20 21:28	General View	 Load JPG	
7	16/08/20 21:28	General View	 Load JPG	
8	16/08/20 21:28	General View	 Load JPG	
9	16/08/20 21:28	General View	 Load JPG	
10	16/08/20 21:28	General View	 Load JPG	
11	16/08/20 21:28	General View	 Load JPG	
12	16/08/20 21:28	General View	 Load JPG	
13	16/08/20 21:28	General View	 Load JPG	
14	16/08/20 21:28	General View	 Load JPG	
15	16/08/20 21:28	General View	 Load JPG	
16	16/08/20 21:28	General View	 Load JPG	
17	16/08/20 21:28	General View	 Load JPG	
18	16/08/20 21:28	General View	 Load JPG	
19	16/08/20 21:28	General View	 Load JPG	
20	16/08/20 21:28	General View	 Load JPG	
21	16/08/20 21:28	General View	 Load JPG	
22	16/08/20 21:28	General View	 Load JPG	
23	16/08/20 21:28	General View	 Load JPG	
24	16/08/20 21:28	General View	 Load JPG	
25	16/08/20 21:28	General View	 Load JPG	
26	16/08/20 21:28	General View	 Load JPG	
27	16/08/20 21:28	General View	 Load JPG	
28	16/08/20 21:28	General View	 Load JPG	
29	16/08/20 21:28	General View	 Load JPG	
30	16/08/20 21:28	General View	 Load JPG	
31	16/08/20 21:28	General View	 Load JPG	
32	16/08/20 21:28	General View	 Load JPG	
33	16/08/20 21:28	General View	 Load JPG	
34	16/08/20 21:28	General View	 Load JPG	
35	16/08/20 21:28	General View	 Load JPG	
36	16/08/20 21:28	General View	 Load JPG	
37	16/08/20 21:28	General View	 Load JPG	
38	16/08/20 21:28	General View	 Load JPG	
39	16/08/20 21:28	General View	 Load JPG	
40	16/08/20 21:28	General View	 Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	16/08/20 21:28	General View	 Load JPG	☒
42	16/08/20 21:28	General View	 Load JPG	☒
43	16/08/20 21:28	General View	 Load JPG	☒
44	16/08/20 21:28	General View	 Load JPG	☒
45	16/08/20 21:28	General View	 Load JPG	☒
46	16/08/20 21:28	General View	 Load JPG	☒
47	16/08/20 21:28	General View	 Load JPG	☒
48	16/08/20 21:28	General View	 Load JPG	☒
49	16/08/20 21:28	General View	 Load JPG	☒
50	16/08/20 21:28	General View	 Load JPG	☒
51	16/08/20 21:28	General View	 Load JPG	☒
52	16/08/20 21:28	General View	 Load JPG	☒
53	16/08/20 21:28	General View	 Load JPG	☒
54	16/08/20 21:28	General View	 Load JPG	☒
55	16/08/20 21:28	General View	 Load JPG	☒
56	16/08/20 21:28	General View	 Load JPG	☒
57	16/08/20 21:28	General View	 Load JPG	☒
58	16/08/20 21:28	General View	 Load JPG	☒
59	16/08/20 21:28	General View	 Load JPG	☒
60	16/08/20 21:28	General View	 Load JPG	☒
61	16/08/20 21:28	General View	 Load JPG	☒
62	16/08/20 21:28	General View	 Load JPG	☒
63	16/08/20 21:28	General View	 Load JPG	☒
64	16/08/20 21:28	General View	 Load JPG	☒
65	16/08/20 21:28	General View	 Load JPG	☒
66	16/08/20 21:28	General View	 Load JPG	☒
67	16/08/20 21:28	General View	 Load JPG	☒
68	16/08/20 21:28	General View	 Load JPG	☒
69	16/08/20 21:28	General View	 Load JPG	☒
70	16/08/20 21:28	General View	 Load JPG	☒
71	16/08/20 21:28	General View	 Load JPG	☒
72	16/08/20 21:28	General View	 Load JPG	☒
73	16/08/20 21:28	General View	 Load JPG	☒
74	16/08/20 21:28	General View	 Load JPG	☒
75	16/08/20 21:28	General View	 Load JPG	☒
76	16/08/20 21:28	General View	 Load JPG	☒
77	16/08/20 21:28	General View	 Load JPG	☒
78	16/08/20 21:28	General View	 Load JPG	☒
79	16/08/20 21:28	General View	 Load JPG	☒
80	16/08/20 21:28	Photographs of Damaged Parts	 Load JPG	☒
81	16/08/20 21:28	Photographs of Damaged Parts	 Load JPG	☒
82	16/08/20 21:28	Photographs of Damaged Parts	 Load JPG	☒
83	16/08/20 21:28	Photographs of Damaged Parts	 Load JPG	☒
84	16/08/20 21:28	Photographs of Damaged Parts	 Load JPG	☒
85	16/08/20 21:28	Photographs of Damaged Parts	 Load JPG	☒
86	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
87	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
88	16/08/20 21:29	Photographs of Damaged Parts	Load JPG	☒
89	16/08/20 21:29	Photographs of Damaged Parts	Load JPG	☒
90	16/08/20 21:29	Photographs of Damaged Parts	Load JPG	☒
91	16/08/20 21:29	Photographs of Damaged Parts	Load JPG	☒
92	16/08/20 21:29	Photographs of Damaged Parts	Load JPG	☒
93	16/08/20 21:29	Photographs of Damaged Parts	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
95	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
96	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
97	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
98	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
99	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
100	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
101	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
102	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
103	16/08/20 21:29	Photographs of Damaged Parts	 Load JPG	☒
104	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
105	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
106	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
107	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
108	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
109	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
110	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
111	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
112	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
113	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
114	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
115	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
116	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
117	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
118	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
119	09/09/20 21:28	Reinspection Photo	 Load JPG	☒
120	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
121	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
122	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
123	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
124	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
125	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
126	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
127	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
128	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
129	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
130	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
131	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
132	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
133	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
134	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
135	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
136	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
137	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
138	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
139	11/09/20 09:04	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/08/20 10:59	LKK EMAIL	 Load PDF	
2	12/08/20 10:59	LKK PREMI ADVISE	 Load PDF	
3	12/08/20 10:59	SBS3198U - TP REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20008261/R1VF3S2**Date:** 07/10/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00056942001	
Claimant Vehicle No :	SBS3198U	Insured Vehicle No :	XE5058R	
Date of Loss:	28/07/2020	Nature of Claim:	TP	Claim No: SNM20D202643/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3198U		Engine No:	D9188052
Make & Model:	VOLVO B9TL, 9.4 D (A)		Chassis No:	YV3S4P92XCA157268
Reg. Date:	30/08/2012 (Man. Year: 2012)		Odometer:	0 km
Colour:	Multi-colour			
Engine Capacity:	9364 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,719.84	9,719.84	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,450.00	7,850.00	600.00	7.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,169.84	17,569.84	600.00	3.30
+ GST 7.00/7.00% (S\$)	1,271.89	1,229.89	42.00	3.30
Nett Amount (S\$)	19,441.73	18,799.73	642.00	3.30

INSPECTION

Date of Assignment:	12/08/2020		
Date Inspected:	11/08/2020	Inspected At:	SBS Transit Ltd 28 SOON LEE ROAD SINGAPORE 628083
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Oct 2020)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3198U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*O/S LOWER ENG ACCESS; SHEET METAL - 30 750 059	Bent	1,620.35 F	*1,620.35 F
2	1	*SIDE SHEET METAL PANEL - 30 750 041	Bent	190.78 F	*190.78 F
3	1	*SIDE SHEET METAL PANEL - 30 750 042	Bent	769.32 F	*769.32 F
4	1	*SIDE SHEET METAL PANEL - 30 750 060	Bent	853.46 F	*853.46 F
5	2	*GLASS.SIDE.4MM.GLAZING - 30 750 007	Broken	500.00 F	*500.00 F
6	1	*GLASS.SIDE.4MM.GLAZING. O/N/S - 30 117 229	Broken	153.96 F	*153.96 F
7	1	*WINDOW RBBR;N/S;O/S BODY; 12MM - 30 117 030	Scratched	85.00 F	*85.00 F
8	1	*TECHNA 6 WAY SWITCH PANEL - VM6 - 30 750 407	Bent	36.01 F	*36.01 F
9	1	*ALLOY CAPPING FOR LOWER DECK SIDE PLLANK - 30 750 383	Bent	84.00 F	*84.00 F
10	2	*SEALED LEVER LATCH; OS/NS; RR SIDE DR - 30 750 003	Broken	68.60 F	*68.60 F
11	2	*CENTRE OS CORNER DEFLECTOR COMP MOULD CL2 - 30 750 000	Necessary	118.00 F	*118.00 F
12	7	*BOSTICK SEALANT 7008 - 30 730 000	Necessary	108.50 F	*108.50 F
13	1	*ALLOY CAPPING	Necessary	84.00 F	*84.00 F
14	1	*SIDE RAIL	Bent	5,047.86 F	*5,047.86 F

F=Franchise part.

Total Parts (S\$) 9,719.84 9,719.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR.	New	5,700.00	5,400.00
2	SPRAY PAINTING.	New	2,750.00	2,450.00
Gross Labour Cost (S\$)			8,450.00	7,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >