

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008271/KVF3E2

Date: 10/09/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30795419011
Claimant Vehicle No :	SKW3658G	Insured Vehicle No :	PC7725R
Date of Loss:	07/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202770

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW3658G		
Make & Model:	MAZDA 3, 1.5 (A)	Engine No:	P520321917
Reg. Date:	27/10/2015 (Man. Year: 2015)	Chassis No:	JM6BM42A8G0320447
Colour:	Metallic Grey	Odometer:	97572 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Nexen 8 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Bridgestone 3 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,196.99	5,788.00	7,408.99	56.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,470.00	1,770.00	54.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,436.99</b>	<b>7,258.00</b>	<b>9,178.99</b>	<b>55.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
<b>(S\$)</b>	16,436.99	5,800.00	10,636.99	64.71
<b>+ GST 7.00/7.00% (S\$)</b>	1,150.59	406.00	744.59	64.71
<b>Nett Amount (S\$)</b>	<b>17,587.58</b>	<b>6,206.00</b>	<b>11,381.58</b>	<b>64.71</b>

### INSPECTION

Date of Assignment: 01/09/2020  
 Date Inspected: 12/08/2020 Inspected At:

S Three Automotive Recovery Pte Ltd  
 (HQ)  
 Blk 8 Sin Ming Industrial Estate, #01-64/66  
 Sector C  
 Singapore 575643

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2020)
<b>Parts:</b>	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW3658G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cut	2,295.00 FL	*2,295.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Serviceable	28.00 FL	*- FL
3	1		*FRONT BUMPER	Buckled / Cut	1,025.00 FL	*1,025.00 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	56.00 FL	*56.00 FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	56.00 FL	*- FL
6	1		*FRONT BUMPER BRACKET LH	Repair	43.00 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Cut	149.30 FL	*149.30 FL
8	1		*FRONT BUMPER FOG LAMP	Mtg Cracked	318.50 FL	*281.90 FL
9	1		*FRONT BUMPER LOWER GRILLE	Serviceable	452.00 FL	*- FL
10	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING	Serviceable	106.48 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Repair	410.00 FL	*- FL
12	1		*FRONT BUMPER LOWER GARNISH	Serviceable	36.00 FL	*- FL
13	1		*FRONT GRILLE LOGO	Necessary	31.20 FL	*31.20 FL
14	1		*FRONT GRILLE	Serviceable	522.00 FL	*- FL
15	1		*FRONT GRILLE CHROME LH	Serviceable	142.20 FL	*- FL
16	1		*FRONT GRILLE CHROME RH	Serviceable	142.20 FL	*- FL
17	1		*FRONT FENDER LH	Bent	325.00 FL	*325.00 FL
18	1		*FRONT FENDER INNER SHIELD LH	Distorted	158.00 FL	*158.00 FL
19	1		*FRONT ABSORBER LH	Serviceable	289.70 FL	*- FL
20	1		*FRONT ABSORBER TOP MOUNTING LH	Serviceable	106.70 FL	*- FL
21	1		*FRONT WHEEL HUB W/BEARING	Necessary	146.80 FL	*146.80 FL
22	1		*FRONT LOWER ARM LH	Distorted	333.90 FL	*333.90 FL
23	1		*FRONT CONTROL ARM LH	Distorted	333.90 FL	*333.90 FL
24	1		*FRONT KNUCKLE ARM LH	Bent	398.00 FL	*398.00 FL
25	1		*FRONT CAPITAL	Serviceable	3,928.00 FL	*- FL
26	1		*WING MIRROR ASSY	Mtg Distorted	786.00 FL	*726.00 FL
27	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*FRONT BUMPER LOWER SPOILER	Serviceable	680.00 FS	*- FS
30	1		*FRONT SPORT RIM LH	Dented / Scratched	680.00 FS	*680.00 FS
31	1		*FRONT TYRE LH	Serviceable	380.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
						<b>Sub Total (\$\$)</b> 14,458.88 7,040.00
						<b>- List Item Discount on L Items 10.00/20.00% (\$\$)</b> 1,261.89 1,252.00
						<b>Total Parts (\$\$)</b> 13,196.99 5,788.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,200.00	500.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,400.00	680.00
3	CHECK AND REPAIR WIRING SYSTEM	New	120.00	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	120.00	30.00
5	R&R FRONT SUSPENSION COMPONENT LH	New	280.00	180.00
6	COMPUTERISED WHEEL ALIGNMENT AND BALANCING TYRE	New	120.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>3,240.00</b>	<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >