



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

INV No. AC2101006

1 RAFFLES QUAY #29-10 SOUTH TOWER  
SINGAPORE 048583

INV Date 17/02/2021  
Reference CC4/QBE20008273/Kes3q2  
Code QBE

### PROFESSIONAL SERVICE FEE

Vehicle No. SMR 4220G  
Insured Veh. SJZ 8229A  
Claim No. VC013856  
Policy No. 8-VX020620-MVA-E001  
Accident Date 10/08/2020  
Inspection Date 12/08/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC4/QBE20008273/Kes3q2	
			Date: 17/02/2021	
			Code: QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJZ 8229A		Veh. Inspected	SMR 4220G
Policy No.	8-VX020620-MVA-E001		Coverage (\$)	0.00
Claim No.	VC013856		Excess (\$)	0.00
Assign From	ANDREW		Assign Date	11/08/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA SHUTTLE (A)		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2020
Chassis No.	GP72001933		Colour	METALLIC BLACK
Odometer	59968 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre		185/60 R15	SUNWIDE	9 mm
L/H Front Tyre		185/60 R15	SUNWIDE	9 mm
R/H Rear Tyre		185/60 R15	YOKOHAMA	7 mm
L/H Rear Tyre		185/60 R15	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/08/2020		Inspection Date	12/08/2020
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 4220G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAILGATE	BENT	986.90	986.90
1	REAR TAILGATE "SHUTTLE" EMBLEM	NECESSARY	46.60	46.60
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	56.20	56.20
8	REAR TAILGATE INNER TRIM CLIPS @\$5.50	NOT NECESSARY	44.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	68.70	68.70
1	REAR BUMPER	BUCKLED	783.70	783.70
8	REAR BUMPER CLIPS @\$5.80	NECESSARY	46.40	46.40
1	REAR TAILLAMP RH (CRACKED)	NOT CONSISTENT WITH THE IMPACT	580.20	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-522.54	-397.70
			2,090.16	1,590.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
2	REAR WINDSCREEN STOPPER @\$15.00 (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	350.00	200.00
			440.00	270.00
<b><u>LABOUR</u></b>				
	LABOUR CHARGES TO REMOVE,REFIX,REPLACE,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	400.00
	LABOUR CHARGES TO REMOVE,REFIX & REPLACE REAR WINDSCREEN GLASS,REAR WINDSCREEN SEALANT,REAR WINDSCREEN MOULDING & ETC.TO EFFECT REPLACE OF REAR TAILGATE & ETC.		150.00	120.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		80.00	50.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC.TO EFFECT REPLACE OF REAR TAILGATE & ETC.		120.00	60.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE,REAR BUMPER,REAR END PANEL & ETC.		700.00	400.00

Report Ref No. CC4/QBE20008273/Kes3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING & ELECTRICAL WIRING SYSTEM.		80.00	20.00
			1,730.00	1,050.00
GRAND TOTAL			4,260.16	2,910.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/QBE20008273/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMR 4220G

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

