

ASS. REC. BY:

Steve

REF:

CS/CT120008275/ut#3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMH99406 Yr Regn: 28/9/15Type: ☒ M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai c.c. 1197Colour: Black A/C: Insured / Std / NI / NASp. Reading: 103023 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STN FEAJ114 1468793Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S / Rim / STD A/Rim orTyre Size: F: 215/6R17R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 7/8/20 D.O.I. 12/8/20Survey held at H S AutomotikDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-SSK</u>
	<u>finalize \$9200 (L/S, before GST). 6 repair days.</u>
	<u>RED: 14204.20; 60%</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L.B. (\$) \_\_\_\_\_

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

HS

PTE. LTD.

## HS AUTOMOTIVES PTE LTD

5 &amp; 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOMOBILE #02-25 SINGAPORE 417921

TEL: 6335 1355 FAX: 6538 1367 Email: hsautomotivesp@hsautomotivesp.com

Vehicle No :

Make/Model :

CHASSIS NO :

Accident Date :

Remarks :

SMH9940G

NISSAN QASHQAI

SINFEA311U1468793

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATES

Date: \_\_\_\_\_

Estimate cost of repair to the above mentioned

UNIT \$ AMOUNT (\$\$) REMARKS

NO.	QTY	List Items			
1		REAR TAILGATE / DD	\$ -	\$ 2988.80	
2		REAR TAILGATE LOGO 'NISSAN' / MC	\$ -	\$ 75	
3		REAR TAILGATE EMBLEM 'QASHQAI' - MC	\$ -	\$ 75	
4		REAR TAILGATE REFLECTOR LAMP (LH & RH) LH ?	\$ 215.40	\$ 431.80	
5		REAR TAILGATE OUTER GARNISH ? / BR	\$ -	\$ 356.10	
6		REAR TAILGATE OUTER GARNISH CHIP ? / MC	\$ -	\$ 18	
7		REAR TAILGATE WIPER MOTOR X	\$ -	\$ 411.70	
8	SW	REAR TAILGATE NUMBER PLATE * / CHT	\$ -	\$ 50	
9		REAR TAILGATE NUMBER PLATE LAMP (LH & RH) X	\$ 86.30	\$ 172.60	
10	SW	REAR TAILGATE REVERSE CAMERA X	\$ -	\$ 550	
11		REAR TAILGATE LOCK MECHANISM / BT	\$ -	\$ 156.70	
12		REAR TAILGATE DAMPER (LH & RH) X	\$ 219.40	\$ 439.60	
13		REAR TAILGATE HINGE (LH & RH) X	\$ 131.10	\$ 262.20	
14		REAR TAILGATE LOWER TRIM BOARD ? / CRU	\$ -	\$ 217.80	
15	SW	REAR TAILGATE LOWER TRIM BOARD CHIP ? / MPE	\$ -	\$ 38	
16		REAR TAILGATE WEATHERSTRIP ? / CRU	\$ -	\$ 168.70	
17		REAR TAILGATE WINDSCREEN RUBBER MOUNTING / MC	\$ -	\$ 217.60	
18	SW	REAR TAILGATE WINDSCREEN SEALANT / MC	\$ -	\$ 100	69
19		REAR BUMPER / DD	\$ -	\$ 757.10	
20	SW	REAR BUMPER CHIP / MC	\$ -	\$ 48	
21		REAR BUMPER SIDE RETAINER (LH & RH) - BR	\$ 45	\$ 90	
22	SW	REAR BUMPER REVERSE SENSOR - BR	\$ -	\$ 350	
23		REAR BUMPER TOW COVER / CHT	\$ -	\$ 45.40	
24		REAR BUMPER REINFORCEMENT ? / BT	\$ -	\$ 659.20	
25		REAR BUMPER INNER SPOUGE ? / BR	\$ -	\$ 126.40	
26		REAR BUMPER WIRELESS ANTENNA ? / OR	\$ -	\$ 99.80	
27		REAR BUMPER REFLECTOR (LH & RH) (LH) / OR	\$ 66.70	\$ 133.40	
28		REAR FENDER (LH & RH) X R	\$ -	\$ -	
29		REAR FENDER INNER SHIELD (LH & RH) ? X	\$ -	\$ -	
30	SW	REAR FENDER INNER SHIELD CHIP (LH & RH) ? / MC	\$ -	\$ -	

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	

HS

## HS AUTOMOTIVES PTE LTD

15-2 KARU BUKIT AVE 2 @ KARU BUKIT AUTOMOBILE 402-20 SINGAPORE 417121

TEL: 6538 1385 FAX: 6538 1367 Email: hsautomotivesp@comnet.com.sg

Vehicle No :

Make/Model :

CHASSIS NO :

Accident Date :

Remarks :

SMH99406

NISSAN QASHQAI

SJNFEAS11U1H68793

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATES

Date: \_\_\_\_\_

Estimate cost of repair to the above mentioned

UNIT \$ AMOUNT (\$\$) REMARKS

NO. QTY List Items

1	REAR	FENDER INNER TRIM BOARD (LH RH) 8X	\$ 361.70	\$ 763.40	
2	S/W	REAR FENDER INNER TRIM BOARD CHIP (LH RH) 2X	\$ 6.8		
3	REAR	FENDER WHEELARCH GARNISH (LH RH) - CRV 127.60	\$ 255.60		
4	S/W	REAR FENDER WHEELARCH GARNISH CHIP (LH RH) 1PC	\$ 58		
5	REAR	TAILGATE OUTER SWITCH X	\$ -	\$ 85	
6	REAR	END PANEL ? / DD	\$ -	\$ 482.60	
7	REAR	END PANEL TOP GARNISH ? / CRV	\$ -	\$ 84.50	
8	S/W	REAR END PANEL TOP GARNISH CHIP ? / MC	\$ -	\$ 16	
9	REAR	SPARE TYRE PANEL X R / DD	\$ -	\$ -	
10	REAR	SPARE TYRE PANEL TOOLS BOX ? / CRV	\$ -	\$ -	
11	REAR	SPARE TYRE PANEL TOP TRIM / CRV	\$ -	\$ -	
12	REAR	SPARE TYRE PANEL TOP TRIM BOARD X	\$ -	\$ -	
13	REAR	EXHAUST PIPE . / OT	\$ -	\$ -	
14	REAR	EXHAUST PIPE TOP MOUNTING X	\$ -	\$ -	
15			\$ -	\$ -	
16			\$ -	\$ -	
17			\$ -	\$ -	
18			\$ -	\$ -	
19			\$ -	\$ -	
20			\$ -	\$ -	
21			\$ -	\$ -	
22			\$ -	\$ -	
23			\$ -	\$ -	
24			\$ -	\$ -	
25			\$ -	\$ -	
26			\$ -	\$ -	
27			\$ -	\$ -	
28			\$ -	\$ -	
29			\$ -	\$ -	
30			\$ -	\$ -	

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

\$ -

SURVEYOR NAME

EMAIL ADD:

CONTACT:

HS

## HS AUTOMOTIVES PTE LTD

11 KAKI BOKIT AVE 2 @ KAKI BOKIT AUTOMOBILE 802-25 SINGAPORE 417921

TEL: 6335 1335 FAX: 6538 1367 Email: info@hsautomotives.com.sg

Vehicle No :

Make/Model :

CHASSIS NO :

Accident Date :

Remarks :

SMH9940G

NISSAN CASHQAI

SS0FEASIKU1468793

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATES

Date: \_\_\_\_\_

Estimate cost of repair to the above mentioned

UNIT \$ AMOUNT (\$\$) REMARKS

NO. QTY	List Items			
1	PAINT REAT & REPLACE PARTS	\$ -	\$2,500	800 900
2		\$ -	\$	
3	PUTTY, REGRAN & POLISH AFFECTED PORTION	\$ -	\$2,400	800 900
4		\$ -	\$	
5	CHECK & RECTIFY WIRING SYSTEM	\$ -	\$150	30
6		\$ -	\$	
7	REMOVE & REFIT REAR WINDSCREEN	\$ -	\$200	120
8		\$ -	\$	
9	REMOVE & TRANSFER TAILGATE COMPONENT	\$ -	\$150	50
10		\$ -	\$	
11	REMOVE & REFIT EXHAUST SYSTEM	\$ -	\$150	80
12		\$ -	\$	
13	REMOVE & INSTALL REVERSE SENSOR	\$ -	\$120	30
14		\$ -	\$	
15	UPHOLSTERY	\$ -	\$250	x
16		\$ -	\$	
17	RUSTPROOF	\$ -	\$100	30
18		\$ -	\$	
19		\$ -	\$	
20		\$ -	\$	
21	Steve (LKK) W/L AL	\$ -	\$	
22		\$ -	\$	
23	12/8/20, 10.30am	\$ -	\$	
24		\$ -	\$	
25	6 days	\$ -	\$	
26		\$ -	\$	
27	L/S	\$ -	\$	
28		\$ -	\$	
29	My AL Jy	\$ -	\$	
		\$ -	\$	
		\$ -	\$	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTACT: