

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008277/R1ES3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993765
Claimant
Vehicle No : SKR5300B **Insured Vehicle No :** SLH9535E
Date of Loss: 10/08/2020 Nature of Claim: TP Claim No: 2116599310SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR5300B**
Make & Model: BMW 218I, 1.5 ACTIVE TOURER D/AB LED DSC Engine No: F2660983B38A15A
AB (A)
Reg. Date: 13/02/2015 (Man. Year: 2014) Chassis No: WBA2A32000VZ50802
Colour: Black Odometer: 36059 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,088.55	2,823.15	2,265.40	44.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,383.00	4,431.00	2,952.00	39.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,471.55	7,254.15	5,217.40	41.83
+ GST 7.00/7.00% (S\$)	873.01	507.79	365.22	41.83
Nett Amount (S\$)	13,344.56	7,761.94	5,582.62	41.83
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,197.39		

INSPECTION

Date of Assignment: 31/08/2020
Date Inspected: 31/08/2020 Inspected At: Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Not Necessary	83.00 FS	*- FS
2	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	625.00 FS	*- FS
3	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
4	1		*TRUNK LID	Bent	1,210.35 FS	*1,210.35 FS
5	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	1,045.45 FS	*1,045.45 FS
6	1		*RR BUMPER LH SIDE GUIDE	Serviceable	61.35 FS	*- FS
7	1		*RR BUMPER RH SIDE GUIDE	Serviceable	61.35 FS	*- FS
8	1		*REAR BUMPER CARRIER	Serviceable	460.40 FS	*- FS
9	1		*SUPPORT	Serviceable	45.55 FS	*- FS
10	1		*RR BUMPER LH INNER SIDE GUIDE	Serviceable	61.35 FS	*- FS
11	1		*RR BUMPER RH INNER SIDE GUIDE	Serviceable	61.35 FS	*- FS
12	2		*GROMMET	Necessary	1.60 FS	*1.60 FS
13	1		*PLAQUE 74MM	Necessary	71.60 FS	*71.60 FS
14	1		*BUMP STOP (10PCS)	Necessary (6Pcs Only)	37.50 FS	*22.50 FS
15	1		*REAR FLAP TOWING EYE PRIMED	Serviceable	43.05 FS	*- FS
16	1		*REAR WINDOW ESG	Not Necessary	657.60 FS	*- FS
17	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS
18	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
19	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
20	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
21	3		*BLIND RIVET NUT M6	Necessary	8.10 FS	*8.10 FS
22	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
23	1		*LETTERING 218I	Necessary	64.45 FS	*64.45 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 5,088.55 2,823.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER PANEL AND ATTACHMENT, BOOTLID REWORK TAIL PANEL	New	3,400.00	1,700.00
2	SPRAY REAR BUMPER, BOOTLID AND TAIL PANEL	New	2,666.00	1,730.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
4	TO REPLACE REAR WINDSCREEN GLASS	New	676.00	676.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	100.00
			Gross Labour Cost (\$)	4,431.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >