

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20008279/KPA3Q2

**Date:** 08/04/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKR8659Y	<b>Insured Vehicle No :</b>	SHD3473H
Date of Loss: 06/08/2020	Nature of Claim: TP	Claim No: MCT20080078

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKR8659Y</b>		
Make & Model:	TOYOTA ESTIMA AERAS, 2.4 PREMIUM (A)	Engine No:	2AZJ130990
Reg. Date:	13/03/2015 (Man. Year: 2014)	Chassis No:	ACR507125643
Colour:	Metallic Grey	Odometer:	94583 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,735.02	1,735.02	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	1,230.00	150.00	10.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,115.02</b>	<b>2,965.02</b>	<b>150.00</b>	<b>4.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>(S\$)</b>	3,115.02	2,350.00	765.02	24.56
<b>+ GST 7.00/7.00% (S\$)</b>	218.05	164.50	53.55	24.56
<b>Nett Amount (S\$)</b>	<b>3,333.07</b>	<b>2,514.50</b>	<b>818.57</b>	<b>24.56</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
<b>Nett Liability (S\$)</b>		<b>2,914.50</b>		

### INSPECTION

Date of Assignment:	07/08/2020	
Date Inspected:	18/08/2020 Inspected At:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01- 04 ANG MO KIO AUTOPOINT Singapore 568047
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2020)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA AERAS 2.4 PREMIUM (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKR8659Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*REAR BUMPER</b>	Buckled	622.10 FL	*622.10 FL
2	5		<b>*REAR BUMPER CLIPS</b>	Necessary	22.50 FL	*22.50 FL
3	1		<b>*TAILGATE LOGO</b>	Necessary	72.20 FL	*72.20 FL
4	1		<b>*TAILGATE EMBLEM ESTIMA</b>	Necessary	49.10 FL	*49.10 FL
5	1		<b>*TAILGATE EMBLEM AERAS</b>	Necessary	57.20 FL	*57.20 FL
6	1		<b>*REAR END PANEL</b>	Bent	755.40 FL	*755.40 FL
7	1		<b>*REAR END PANEL INNER TOP GARNISH</b>	Mtg Cracked	308.20 FL	*308.20 FL
8	1		<b>*SET REVERSE SENSOR</b> (4 PCS)	Scratched	280.00 FS	*280.00 FS
9	1		<b>*REAR END PANEL SEALANT</b>	Necessary	40.00 FS	*40.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					<b>Sub Total (\$\$)</b>	<b>2,206.70</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>471.68</b>
					<b>Total Parts (\$\$)</b>	<b>1,735.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE AND REFIT REAR BUMPER ,TAILLAMP ,CUT ,WELD REAR END PANEL AND REALIGN THE SAME	New	600.00	540.00
2	PUTTY AND RESPRAY REAR BUMPER ,PARKING SENSORS ,TAILGATE ,REAR END PANEL AND ALL AFFECTED AREAS	New	600.00	600.00
3	REMOVE AND REFIX REAR FENDER GARNISH TO FACILITATE REPAIR	New	150.00	60.00
4	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,380.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**