

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20008280/AVF3E2

**Date:** 24/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070086759
<b>Claimant Vehicle No :</b> SMA4808B	<b>Insured Vehicle No :</b>	YP2529Z
Date of Loss: 06/08/2020	Nature of Claim: TP	Claim No: 5404143495SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4808B	Engine No:	L15B5462729
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81202360
Reg. Date:	08/06/2018 (Man. Year: 2018)	Odometer:	95441 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,301.12	1,278.40	1,022.72	44.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	810.00	1,540.00	65.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,651.12</b>	<b>2,088.40</b>	<b>2,562.72</b>	<b>55.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,651.12</b>	<b>1,650.00</b>	<b>3,001.12</b>	<b>64.52</b>

### INSPECTION

Date of Assignment:	11/08/2020	
Date Inspected:	11/08/2020 Inspected At:	10 Kaki Bukit Road 2 #01-21 First East Centre
		Repairer : Polymath Garage Pte Ltd (HQ)
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	956.40 FL	*956.40 FL
2	1		*REAR BUMPER SIDE HOLDER RH	Necessary	38.50 FL	*38.50 FL
3	1		*REAR BUMPER SIDE COVER RH	Not Necessary	53.90 FL	*- FL
4	1		*REAR BUMPER SIDE REFLECTOR RH	Cracked	45.10 FL	*45.10 FL
5	1		*TAILLAMP RH	Cracked	520.50 FL	*520.50 FL
6	1		*REAR FENDER RH	Repair	1,099.50 FL	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
8	1		*REAR FENDER GLASS SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,843.90</b>	<b>1,590.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	542.78	312.10
<b>Total Parts (\$\$)</b>	<b>2,301.12</b>	<b>1,278.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,000.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	400.00
3	WIRING CHECK	New	50.00	30.00
4	TUFF COAT	New	150.00	30.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
7	TO REMOVE FENDER GLASS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,350.00</b>	<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >