



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2102428

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 10/04/2021
Reference CC4/LPC20008283/Dga3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. JSL 6612
Insured Veh. SLX 813C
Claim No. 19/20/20/VP05/023525
Policy No. Z19VP05025308
Accident Date 06/08/2020
Inspection Date 12/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20008283/Dga3q2	Date: 10/04/2021
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 813C	Veh. Inspected	JSL 6612	
Policy No.	Z19VP05025308	Coverage (\$)	0.00	
Claim No.	19/20/20/VP05/023525	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	11/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA Y15ZR	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	PMYUG0510H0117070	Colour	BLUE / SILVER	
Odometer	52448 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/80 R17	MAXXIS	2 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/70 R17	MAXXIS	2 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2020	Inspection Date	12/08/2020	
Survey held at	S9 MOTOR TRADING PTE LTD BLK.4001 #01-21 ANG MO KIO INDUSTRIAL PARK 1 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSL 6612

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PILLAR GRIP	NOT NECESSARY	95.00	-
1	REAR MUDGUARD	BROKEN	235.00	235.00
1	EXHAUST PIPE	NOT NECESSARY	650.00	-
1	EXHAUST GUARD-NOZZLE	NOT NECESSARY	280.00	-
1	EXHAUST CENTRE GUARD	NOT NECESSARY	250.00	-
1	REAR LH SIGNAL	BROKEN	90.00	90.00
1	CLUTCH LEVER	NOT NECESSARY	85.00	-
1	HANDLE BAR	NOT NECESSARY	155.00	-
1	REAR RIM	NOT NECESSARY	320.00	-
1	REAR LH SIDE PANEL	CUT	185.00	185.00
1	SET BALANCER	CUT	160.00	160.00
1	FRONT RIM	DISTORTED	380.00	380.00
1	FRONT LH SIDE PANEL	CUT	168.00	168.00
	LESS 10% DISCOUNT		-305.30	-121.80
			2,747.70	1,096.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	15.00	15.00
1	NUMBER PLATE HOLDER (SN)	NOT NECESSARY	85.00	-
1	ONE SET BODY DECAL STICKER (SN)	NECESSARY	120.00	80.00
			220.00	95.00
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS.ALIGN & ETC.		250.00	150.00
	REMOVE & REPLACE RIM & CHECK FORK ASSY.		200.00	80.00
			490.00	230.00
	GRAND TOTAL		3,457.70	1,421.20

Report Ref No. CC4/LPC20008283/Dga3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00
---	--	--	-----------------

Report Ref No. CC4/LPC20008283/Dga3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JSL 6612

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JSL 6612

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. JSL 6612

RE-INSPECTION

