

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20008288/GGS3Q2
Date: 17/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070090917
Claimant Vehicle No :	SMH7086K	Insured Vehicle No :	GBG1067R
Date of Loss:	06/08/2020	Nature of Claim:	TP
		Claim No:	9747128394SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7086K	Engine No:	HIDDEN
Make & Model:	BLUECAR BLUECAR, (A)	Chassis No:	VL4BCEB4RJT003458
Reg. Date:	30/01/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,196.45	6,915.85	280.60	3.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,140.00	1,310.00	53.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,646.45	8,055.85	1,590.60	16.49
+ GST 7.00/7.00% (S\$)	675.25	563.91	111.34	16.49

Nett Amount (S\$)	10,321.70	8,619.76	1,701.94	16.49
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,101.76		

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Indeco Engineers Pte Ltd (Defu)
No. 39 Defu Lane 12
Singapore 539315

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY (WCP)	Cracked	1,364.00 F	*1,364.00 F
2	10		*REAR BUMPER SCREW (WCP)	Necessary	20.00 F	*20.00 F
3	1		*REAR BUMPER REFLECTOR LH (WCP)	Serviceable	122.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT (WCP)	Serviceable	80.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH (WCP)	Serviceable	42.00 F	*- F
6	1		*LH TAILLAMP ASSY (WCP)	Cracked	147.00 F	*147.00 F
7	1		*TAILLAMP COVER LH (WCP)	Cracked	282.00 F	*282.00 F
8	1		*REAR LH FENDER COVER (WCP)	Cut	189.00 F	*189.00 F
9	4		*REAR LH FENDER COVER NUTS (WCP)	Necessary	4.00 F	*4.00 F
10	1		*REAR LH FENDER INNER SHIELD (WCP)	Deformed	150.00 F	*150.00 F
11	8		*REAR LH FENDER INNER SHIELD CLIPS(WCP)	Necessary	16.00 F	*16.00 F
12	1		*REAR FENDER PANEL LH (WCP)	Distorted	3,807.00 F	*3,807.00 F
13	1		*REAR FENDER STICKER PANEL (WCP)	Necessary	40.00 FS	*40.00 FS
					Sub Total (\$\$)	6,263.00
					+ Margin on L,N Items 15.00/15.00% (\$\$)	933.45
					Total Parts (\$\$)	7,196.45
						6,019.00
						896.85
						6,915.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR ,REPLACE REAR BUMPER ,REINFORCEMENT ,BRACKET ,REAR LEFT FENDER ,COVER ,INNER SHIELD ,LH TAILLAMP ASSY & COVER ,REFLECTOR ,STICKER AND AFFECTED AREA	New	1,500.00	800.00
2	TO PUTTY AND RESPRAY ON REAR BUMPER .REAR LEFT FENDER AND AFFECTED AREA	New	700.00	250.00
3	TO APPLY TUFF KOTE	New	150.00	60.00
4	TO CHECK WIRING	New	100.00	30.00
Gross Labour Cost (\$\$)			2,450.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >