

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008290/KPS3Q2

Date: 13/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SLT1156E	Insured Vehicle No :	SH6232R	
Date of Loss: 07/08/2020	Nature of Claim: TP	Claim No:	MCT20080085

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1156E		
Make & Model:	BMW 530I, 3.0 (A)	Engine No:	16409958B48B20B
Reg. Date:	17/10/2017 (Man. Year: 2017)	Chassis No:	WBAJA52090G885833
Colour:	Metallic Dark Blue	Odometer:	64245 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,920.62	5,675.32	10,245.30	64.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,738.00	3,068.00	4,670.00	60.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,658.62	8,743.32	14,915.30	63.04
+ GST 7.00/7.00% (S\$)	1,656.10	612.03	1,044.07	63.04
Nett Amount (S\$)	25,314.72	9,355.35	15,959.37	63.04
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,162.80		

INSPECTION

Date of Assignment:	12/08/2020	
Date Inspected:	13/08/2020	Inspected At: TTS Eurocars Pte Ltd (Sin Ming) 383 Sin Ming Drive, TTS Centre Singapore 575717
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2020)
Parts:	143	BMW 530I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1156E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Bent	1,161.42 FL	*985.00 FL
2	1		*FRONT RH FENDER GRILLE	Serviceable	99.54 FL	*- FL
3	1		*FRONT RH SIDE MIRROR	Serviceable	1,623.34 FL	*- FL
4	1		*FRONT RH DOOR	Bent	2,186.96 FL	*2,186.96 FL
5	1		*DOOR HINGE TOP	Repair	90.51 FL	*- FL
6	1		*DOOR HINGE BOTTOM	Serviceable	90.51 FL	*- FL
7	1		*DOOR WINDO REGULATOR	Serviceable	528.58 FL	*- FL
8	1		*DOOR WINDOW MOTOR	Serviceable	419.10 FL	*- FL
9	1		*DOOR WEATHER STRIP	Necessary	289.58 FL	*289.58 FL
10	1		*WEATHERSTRIP COLUMN B	Not Necessary	106.44 FL	*- FL
11	1		*WEATHERSTRIP EXTERNAL LINE	Not Necessary	182.02 FL	*- FL
12	1		*WEATHERSTRIP WINDOW FRAME	Not Necessary	264.84 FL	*- FL
13	1		*REAR DOOR RH	Repair	2,386.98 FL	*- FL
14	1		*DOOR HINGE TOP	Repair	90.51 FL	*- FL
15	1		*DOOR HINGE BOTTOM	Repair	90.51 FL	*- FL
16	1		*SIDE SKIRT RH	Dented	660.32 FL	*660.32 FL
17	1		*SUPPORT LEDGE BACK	Serviceable	43.57 FL	*- FL
18	1		*SUPPORT LEDGE MID	Serviceable	43.57 FL	*- FL
19	1		*SUPPORT LEDGE EDGE	Serviceable	43.57 FL	*- FL
20	1		*REAR DOOR CARRIER (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*REAR DOOR WINDOW LIFTER	Serviceable	628.58 FL	*- FL
22	1		*REAR DOOR WEATHERSTRIP	Serviceable	289.58 FL	*- FL
23	1		*REAR DOOR GAP SEAL	Serviceable	76.39 FL	*- FL
24	1		*DOOR WEATHER STRIP COLUMN B	Serviceable	137.90 FL	*- FL
25	1		*DOOR WEATHER STRIP EXTERNAL LINE	Serviceable	132.86 FL	*- FL
26	1		*DOOR WEATHER STRIP EXTERNAL LINE	Serviceable	132.86 FL	*- FL
27	1		*REAR RH FENDER	Repair	2,458.67 FL	*- FL
28	1		*SUNDRIES	Not Necessary	150.00 FS	*- FS
29	1		*ALLOY RIM	Dented	1,954.73 FL	*1,954.73 FL
30	1		*WHEEL ELECTRO MODULE	Necessary	229.32 FL	*229.32 FL
31	1		*SUNDRIES	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,742.76	6,305.91
- List Item Discount on L Items 5.00/10.00% (\$\$)	822.14	630.59
Total Parts (\$\$)	15,920.62	5,675.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CERAMIC COATING	New	488.00	488.00
2	WHEEL BALANCING ALIGNMENT	New	50.00	50.00
3	WIRING CONNECTION AND CHECK	New	150.00	30.00
4	TUFF KOTE AND SPRAY ANTI RUST PROOFING	New	350.00	60.00
5	SEALANT FOR FRONT RH DOOR ,REAR RH DOOR	New	250.00	60.00
6	TO REMOVE AND REPLACE FRONT RH DOOR ,DISMANTLE DOOR COMPONENTS ,SCUFF PLATES TRIM BOARDS	New	350.00	0.00
7	TO REMOVE AND REPLACE REAR RH DOOR ,DISMANTLE DOOR COMPONENTS ,SCUFF PLATES TRIM BOARDS	New	350.00	0.00
8	TO CONDUCT DOOR FREQUENCY TEST ,CALIBRATE DOOR KEYLESS ENTRY PROGRAMME ,INSTALL DOOR CONDUCT ACUTUATION	New	350.00	150.00
9	TO REMOVE AND REFIG/REPLACE FRONT RH SIDE MIRROR	New	150.00	0.00
10	LABOUR CHARGES TO DISMANTLE & REFIX FRONT BUMPER FRONT RH FENDER ,FRONT RH DOOR ,REAR RH DOOR REAR RH FENDER ,RH SIDE SKIRT ,RH ROCKER PANEL RH SIDE MIRROR ,RH B PILLAR AND ALL OTHER AFFECTED AREAS TO REPAIR AND ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION	New	2,000.00	800.00
11	TO PUTTY ,SAND ,SRPAY PAINT ,POLISH AND WAX FRONT BUMPER ,FRONT RH FENDER ,FRONT RH DOOR REAR RH DOOR ,REAR RH FENDER ,RH SIDE SKIRT RH ROCKER PANEL ,RH B PILLAR AND ALL OTHER AFFECTED AREAS	New	2,000.00	1,100.00
12	TO CONDUCT AND PROGRAMME 360 DEGREE SENSOR CALIBRATE ACTUETE DISTANCE SETTING .INTEGRATION AND ADAPTATION	New	550.00	180.00
13	REMOVE AND REFIX/FRONT BUMPER SENSOR	New	150.00	0.00
14	TO CONDUCT ECU PROGRAMMING ,CHECK AND CLEAR FAULT CODES ,RESTORE PROGRAMME MODULES	New	550.00	150.00
Gross Labour Cost (\$\$)			7,738.00	3,068.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >