

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20008297/ESF3Q2

Date: 04/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant
Vehicle No : SMH8695X

Insured Vehicle No : SLJ8358X

Date of Loss: 06/08/2020

Nature of Claim: TP

Claim No: 627054

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH8695X**

Make & Model: HONDA FIT, 1.3 (A)

Engine No: LEB1445219

Reg. Date: 13/02/2019 (Man. Year: 2018)

Chassis No: GP51337403

Colour: Grey

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size:

185/55 R15

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,368.24	7,849.20	16,519.04	67.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,440.00	3,000.00	3,440.00	53.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,808.24	10,849.20	19,959.04	64.78
Approved Total (Overridden) (S\$)		8,700.00		
(S\$)	30,808.24	8,700.00	22,108.24	71.76
+ GST 7.00/7.00% (S\$)	2,156.58	609.00	1,547.58	71.76
Nett Amount (S\$)	32,964.82	9,309.00	23,655.82	71.76

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020 Inspected At:

MY CAR CONSULTANT PTE LTD
53 UBI AVENUE 1 #01-33 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2020)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8695X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	880.20 FL	*880.20 FL
2	2		*TAILGATE STOPPER	Not Necessary	57.00 FL	*- FL
3	1		*TAILGATE INNER LOCK	Bent	167.30 FL	*167.30 FL
4	2		*TAILGATE DAMPER	Not Necessary	318.00 FL	*- FL
5	2		*TAILGATE HINGE	Not Necessary	82.00 FL	*- FL
6	1		*TAILGATE STIRICKER	Not Necessary	55.60 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Crushed	99.20 FL	*99.20 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed	486.60 FL	*350.00 FL
9	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	336.20 FL	*- FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	145.00 FL	*145.00 FL
11	1		*TAILGATE EMBLEM	Necessary	68.00 FL	*68.00 FL
12	1		*TAILGATE EMBLEM FIT	Necessary	62.00 FL	*62.00 FL
13	1		*TAILGATE EMBLEM HYBRID	Necessary	82.00 FL	*82.00 FL
14	1		*TAILGATE DETECTOR	Not Necessary	88.20 FL	*- FL
15	1		*TAILGATE KEY DETECTOR	Not Necessary	62.00 FL	*- FL
16	2		*TAILGATE REFLECTOR	Not Necessary	590.00 FL	*- FL
17	2		*REAR NUMBER PLATE LAMP	Not Necessary	108.00 FL	*- FL
18	1		*REAR BUMPER	Dented	512.00 FL	*512.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Broken	116.60 FL	*116.60 FL
20	2		*REAR BUMPER REFLECTOR	Not Necessary	164.00 FL	*- FL
21	2		*REAR BUMPER SIDE GARNISH	Not Necessary	158.00 FL	*- FL
22	1		*REAR BUMPER DIFFUSER	Dented	182.00 FL	*182.00 FL
23	2		*TAILAMP	Cut / Broken	884.00 FL	*884.00 FL
24	2		*TAILAMP PANEL	Repair	550.00 FL	*- FL
25	1		*REAR FENDER	O/S Dented	1,318.00 FL	*659.00 FL
26	2		*REAR FENDER COWLING	Not Necessary	318.00 FL	*- FL
27	1		*REAR FENDER QUARTER GLASS MOULDING	O/S Necessary	282.00 FL	*141.00 FL
28	2		*REAR FENDER INNER TRIM	Deformed	540.00 FL	*540.00 FL
29	1		*REAR END PANEL	Dented	421.00 FL	*421.00 FL
30	1		*REAR END PANEL TOP GARNISH	Crushed	130.20 FL	*130.20 FL
31	1		*REAR FLOOR PANEL	Repair	891.20 FL	*- FL
32	1		*REAR FLOOR PANEL TOP BOARD	Deformed	554.70 FL	*215.90 FL
33	1		*REAR FLOOR PANEL TOP BOARD TRAY	Crushed	498.00 FL	*256.10 FL
34	1		*REAR SPARE TYRE BOLT	Not Necessary	19.50 FL	*- FL
35	1		*SET REAR HYBRID BATTERY SYSTEM	Broken / Bent	16,000.00 FL	*3,250.00 FL
36	1		*EXHAUST SILENCER	Not Necessary	468.00 FL	*- FL
37	1		*EXHAUST PIPE HEAT SHIELD	Not Necessary	114.30 FL	*- FL
38	2		*EXHAUST PIPE SILENCER MOUNTING	Not Necessary	64.00 FL	*- FL
39	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
40	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
41	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*30.00 FS
42	1		*SET TAILAMP CLIPS	Not Necessary	30.00 FS	*- FS
43	2		*TAILAMP SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
45	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
46	2		*REAR FENDER SEALANT	Necessary	200.00 FS	*30.00 FS
47	1		*SET REAR FENDER SIDE INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
48	2		*REAR FENDER QUARTER GLASS SEALANT	Necessary	100.00 FS	*20.00 FS
49	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
50	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
51	1		*REAR FLOOR PANEL INSULATOR	Necessary	250.00 FS	*30.00 FS
52	1		*REAR FLOOR PANEL SEALANT	Necessary	200.00 FS	*30.00 FS
53	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
54	1		*SET REVERSE SENSOR	Broken	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,942.80	9,681.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,574.56	1,832.30

Total Parts (\$\$)	24,368.24	7,849.20
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON AFFECTED AREAS	New	2,200.00	1,000.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	1,300.00
3	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
5	REMOVE AND REFIX REAR UPHOLSTERY	New	400.00	50.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
7	REMOVE AND REFIT TAILGATE MECHANISM	New	150.00	50.00
8	CHECK AND TEST FOR WATER LEAKAGE	New	50.00	30.00
9	REMOVE AND REFIX FUEL TANK TO FACILITATE REPAIR	New	200.00	0.00
10	REMOVE AND REFIX REAR FENDER QUATER GLASS	New	100.00	30.00
11	CHECK AND RESET FAULT CODE LIGHT ON	New	250.00	0.00
12	RESETTING HYBRID SYSTEM AND PROGRAMM ECU	New	600.00	300.00
13	CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
14	TO RESPRAY UNDERCOATING	New	100.00	30.00
15	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (\$\$)			6,440.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >