

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008303/AES3Q2

Date: 08/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900111358

Claimant
Vehicle No : SLP7403Z **Insured Vehicle No :** SMJ4364S

Date of Loss: 08/08/2020 Nature of Claim: TP Claim No: 0086721010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7403Z		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4407215
Reg. Date:	16/06/2017 (Man. Year: 2016)	Chassis No:	RU11207212
Colour:	Black	Odometer:	150465 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,827.40	6,919.76	4,907.64	41.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	2,320.00	670.00	22.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,817.40	9,239.76	5,577.64	37.64
Approved Total (Overridden) (\$\$)		7,300.00		
Nett Amount (\$\$)	14,817.40	7,300.00	7,517.40	50.73
+ Car Rental (7.0 x \$100.00/day) (\$\$)		700.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,007.45		

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020 Inspected At:

Kiang Motor Car Repair Works (HQ)
53 Paya Ubi Industrial Park 1 #01-33
Singapore 408934
Singapore 408934

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	821.10 F	*821.10 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	224.00 F	*- FL
3	1		*REAR BOOT LID EMBLE LOGO	Necessary	55.00 F	*55.00 FL
4	1		*REAR BOOT LID VEZEL LOGO	Necessary	38.10 F	*38.10 FL
5	2		*REAR BOOT LID SIDE REFLECTOR	Cut	776.40 F	*776.40 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	237.00 F	*237.00 FL
7	1		*REAR BOOT LID INNER LOCK	Damaged	284.20 F	*284.20 FL
8	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 F	*50.00 FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	122.20 F	*- FL
10	1		*REAR BOOT LID CENTER MOULDING	Cracked	320.80 F	*320.80 FL
11	10		*REAR BOOT LID INNER TRIM BOARD CLIPS	Necessary	50.00 F	*30.00 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	388.20 F	*388.20 FL
13	2		*REAR TAIL LAMP	Cut	830.40 F	*830.40 FL
14	1		*REAR END PANEL	Distorted	420.00 F	*420.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	188.00 F	*188.00 FL
16	1		*REAR BUMPER	Distorted	845.20 F	*845.20 FL
17	1		*REAR BUMPER LOWER COVER	Deformed	228.00 F	*228.00 FL
18	2		*REAR BUMPER SIDE BRACKET	Necessary	178.40 F	*75.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Not Necessary	425.00 F	*- FL
20	2		*REAR BUMPER SIDE REFLECTOR	Cracked	132.00 F	*132.00 FL
21	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
22	2		*REAR SIDE BUMPER	Repair	450.00 F	*- FL
23	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
24	2		*REAR FENDER INNER TRIM BOARD	Cracked	736.00 F	*736.00 FL
25	1		*REAR EXHAUST	Repair	825.10 F	*- FL
26	1		*REAR EXHAUST ALUMINIUM COVER	Crumpled	84.00 F	*84.00 FL
27	1		*REAR WINDSCREEN MOULDING	Necessary	158.00 F	*158.00 FL
28	1		*REAR SPARE TIRE PANEL	Distorted	1,045.30 F	*1,045.30 FL
29	1		*REAR SPARE TIRE PANEL LOWER COVER	Repeated	428.00 F	*- FL
30	2		*REAR SPARE TIRE PANEL TOP COVER	Deformed	306.00 F	*306.00 FL
31	1		*REAR SPARE TIRE PANEL TOOLS SPONGE	Deformed	226.00 F	*226.00 FL
32	1		*REAR ANTENNA BUZZER	Cracked	85.00 F	*85.00 FL
33	1		*REAR CAMERA	Not Necessary	480.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,827.40 8,599.70
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,679.94

Total Parts (\$\$) 11,827.40 6,919.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	80.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIX REAR EXHAUST	New	280.00	80.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
6	TUFF KOTE	New	120.00	60.00
7	TO CHECK WIRING SYSTEM	New	80.00	30.00
8	PANEL BEATING	New	1,000.00	1,000.00
9	SPRAY PAINTING	New	1,000.00	800.00
10	TO REMOVE AND REFIX REAR CAMERA	New	100.00	50.00
Gross Labour Cost (\$\$)			2,990.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >