

SCL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 20100228E

VEHICLE INSPECTION REPORT

To: Ngee Huat Electrical Trading
C/o: Rui Chuan Car Repairing
Blk 3006 Ubi Road 1 #01-340
Singapore 408700

Date : 3 August 2020
Our ref : RC/07/2001/TP

Accident Date : 13 July 2020
Inspection Date : 21 July 2020
Repairer Name : Rui Chuan Car Repairing
Blk 3006 Ubi Road 1 #01-340
Singapore 408700

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : GZ 5557 H
Make / Model : Toyota Dyna 150
Chassis No : JTFUF34Y103011953
Engine No : 5L5654324

Year / Capacity : 2006 / 2986 cc
Colour : Blue
Mileage : 180667

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	185 R14	5 mm	Normal
Front Offside	: Bridgestone	185 R14	5 mm	Normal
Rear Nearside	: Westlake	155 R12	5.00 / 5.00 mm	Normal
Rear Offside	: Westlake	155 R12	5.00 / 5.00 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 82 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 5,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: GZ 5557 H

Our Ref No: RC/07/2001/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front n/s side black garnish X SVC	Damage	\$ 199.75	\$ 199.75	X
1	Front n/s headlamp ✓	Damage	\$ 1,080.50	\$ 1,080.50	✓
1	Front n/s side mirror X SVC	Damage	\$ 285.95	\$ 285.95	X
1	Front n/s side mirror stay X SVC	Damage	\$ 305.10	\$ 305.10	X
1	Front n/s side mirror lower garnish X SVC	Damage	\$ 221.50	\$ 221.50	X
1	Front panel	Repair	\$ 1,066.50		
1	Front n/s corner panel ✓	Damage	\$ 276.50	\$ 276.50	✓
1	Front grille X SVC	Damage	\$ 648.69	\$ 648.69	X
1	Front grille clip set X SVC	Necessary	\$ 68.50	\$ 68.50	X
1	Front bumper ✓	Damage	\$ 682.80	\$ 682.80	✓
1	Front bumper reinforcement X SVC	Damage	\$ 221.30	\$ 221.30	X
1	Front n/s door X Repair	Damage	\$ 1,568.60	\$ 1,568.60	X
1	Front n/s door lettering ✓	Damage	\$ 45.00	\$ 45.00	✓
1	Front n/s door rubber X SVC	Necessary	\$ 190.05	\$ 190.05	X
1	Front n/s door pillar	Repair	\$ 489.50		
1	N/S step panel garnish X SVC	Damage	\$ 325.50	\$ 325.50	X
			\$ 7,675.74	\$ 6,119.74	2084.8
			Less 25%	\$ 1,918.94	
Total Cost - List Items			\$ 5,756.81	\$ 4,589.81	1563.6

Total cost of parts

\$ 5,756.81 \$ 4,589.81

Vehicle Registration No: GZ 5557 H

Our Ref No: RC/07/2001/TP

S/No	Description	Repairer's Estimate	Revised Amount	
Total cost of parts c/f		\$ 5,756.81	\$ 4,589.81	
<u>LABOUR</u>				
1	To check wiring , lighting and resetting headlamps focussing.	\$ 80.00	\$ 50.00	30
2	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$ 150.00	\$ 120.00	60
3	To apply undercoating on repaired and replaced panel.	\$ 150.00	\$ 90.00	×
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,400.00	\$ 1,000.00	400
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ 880.00	700
GRAND TOTAL		\$ 8,736.81	\$ 6,729.81	

2753.6

-20%: 2200

4 days

Vehicle Registration No: GZ 5557 H

Our Ref No: RC/07/2001/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser









































H

