Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008308/EQF3E2

Date: 18/08/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100319239 Claimant Vehicle FBP2374A Insured Vehicle No: SKH440R

ΤP Date of Loss: 27/06/2020 Nature of Claim: Claim No: 4018020500SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBP2374A Reg No:

Make & Model: YAMAHA SNIPER, 150cc Engine No: HIDDEN

Reg. Date: (Man. Year:) Chassis No: MH3UG0740K0149305

Colour: Blue Odometer: 30121 km

Engine Capacity: 150 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

110/50 R17 120/60 R17 Front Tyre Size: Rear Tyre Size: Front Left Side: Rear Left Side: Dunlop 5 mm Dunlop 5 mm

Rear Right Side: Front Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

12/08/2020 Date of Assignment:

12/08/2020 Inspected At: Date Inspected: Equator Brotherhood (HQ)

25 kaki bukit rd 4 #03-79 synergy @ kb

Singapore 417800

Estimated Period of Repair: 4.0 days

CHEN TSUE YEE Adjuster: Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT TYRE	Torn	0.00 F	*- F
3	1		*FRONT RIM	Cut	0.00 F	*- F
4	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
5	1		*FRONT BRAKE DISC	Bent	0.00 F	*- F
6	2		*FRONT FORK ASSY	Bent	0.00 F	*- F
7	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
8	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
9	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
10	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
11	1		*IGNITION KEY ASSY	Bent	0.00 F	*- F
12	1		*STEERING CONE	Necessary	0.00 F	*- F
13	1		*HANDLE BAR	Bent	0.00 F	*- F
14	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
15	1		*CLUTCH LEVER	Cut	0.00 F	*- F
16	1		*SIDE FAIRING	Cut	0.00 F	*- F
17	1		*FAIRING SHIELD (FRONT)	Broken	0.00 F	*- F
18	3		*CENTER FAIRING	Broken	0.00 F	*- F
19	2		*FAIRING LOWER	Broken	0.00 F	*- F
20	1		*RADIATOR	Bent	0.00 F	*- F
21	1		*FRONT FOOT REST	Cut	0.00 F	*- F
22	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
23	1		*STICKER	Necessary	0.00 F	*- F
24	1		*BASKET	Bent	0.00 F	*- F
25	2		*SIDE LAMP	Cut	0.00 F	*- F
⊢=Fra	anchise	part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >