

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008312/KKS3Q2

**Date:** 29/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100471902
<b>Claimant</b>		
<b>Vehicle No :</b> SJD5226T	<b>Insured Vehicle No :</b>	SJD1819J
Date of Loss: 05/08/2020	Nature of Claim: TP	Claim No: 1048884222SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJD5226T</b>		
Make & Model:	HONDA ODYSSEY, 2.3 (A)	Engine No:	K24A65003371
Reg. Date:	26/03/2008 (Man. Year: 2007)	Chassis No:	JHMRB18508C203371
Colour:	Metallic Black	Odometer:	186896 km
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55Z R17	Rear Tyre Size:	215/55Z R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,866.80	2,889.20	5,977.60	67.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	1,760.00	1,400.00	44.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,026.80</b>	<b>4,649.20</b>	<b>7,377.60</b>	<b>61.34</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,700.00</b>		
<b>Nett Amount (\$\$)</b>	<b>12,026.80</b>	<b>3,700.00</b>	<b>8,326.80</b>	<b>69.24</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	12/08/2020	
Date Inspected:	17/08/2020	Inspected At: A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650 Singapore 680113
Estimated Period of Repair:	6.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,370.00 FL	*- FL
2	1		*TAILGATE LOGO	Necessary	78.00 FL	*78.00 FL
3	1		*TAILGATE REFLECTOR CENTRE	Serviceable	263.00 FL	*- FL
4	1		*TAILGATE REFLECTOR LH/RH	O/S Cracked	884.00 FL	*442.00 FL
5	1		*TAILGATE LOCK	Repair	216.00 FL	*- FL
6	1		*TAILGATE LOCK STRIKER	Repair	38.00 FL	*- FL
7	1		*TAILGATE LOWER GARNISH	Dented / Cut	369.00 FL	*369.00 FL
8	1		*TAILGATE WEATHERSTRIP	Serviceable	138.00 FL	*- FL
9	1		*REAR BUMPER	Buckled	1,198.00 FL	*1,198.00 FL
10	1		*REAR BUMPER REFLECTOR RH	Serviceable	76.00 FL	*- FL
11	2		*REAR BUMPER RETAINER RH	Distorted	113.00 FL	*113.00 FL
12	1		*REAR BUMPER TOW COVER	Serviceable	45.00 FL	*- FL
13	1		*REAR END PANEL	*Check	685.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Serviceable	168.00 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH LOCK STRIKER COVER	Serviceable	33.00 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH INNER COVER	Serviceable	78.00 FL	*- FL
17	1		*TAILLAMP RH	Broken	899.00 FL	*899.00 FL
18	1		*REAR FENDER RH	*Check	1,123.00 FL	*- FL
19	1		*REAR FENDER INNER TRIM RH	Serviceable	866.00 FL	*- FL
20	1		*EXHAUST MUFFLER	*Check	1,280.00 FL	*- FL
21	1		*EXHAUST HEAT SHIELD	Repair	118.00 FL	*- FL
22	1		*REAR WHEEL INNER GARNISH RH	*Check	183.00 FL	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
25	1		*SET REVERSE SENSOR (4 PCS)	Dented	380.00 FS	*320.00 FS
26	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
27	1		*REAR FENDER QUARTER GLASS SEALANT	*Check	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,911.00</b>	<b>3,509.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,044.20	619.80
<b>Total Parts (\$\$)</b>	<b>8,866.80</b>	<b>2,889.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,000.00	700.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,200.00	800.00
3	WIRING CHARGES	New	50.00	20.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	60.00
5	TRANSFER TAILGATE COMPONENT	New	250.00	60.00
6	REMOVE/REFIX TAILGATE WINDSCREEN GLASS	New	180.00	120.00
7	REMOVE/REFIX REAR FENDER QUARTER GLASS (*Check)	New	180.00	0.00
8	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS (*Check)	New	180.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,160.00</b>	<b>1,760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >