

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JODAN CHIN WEI LIANG
BLK 175 BISHAN ST 13 #05-163
SINGAPORE 570175

Contact : 96730468

TP Chin
Veron

ESTIMATE

Repair Code : CLM16370

Date in : 11/08/2020

Vehicle Num. : SBV3918T

Model : TOYOTA COROLLA 1.3M

Chassis/Eng# : EE1013032927/4E0495721

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehd</i>	1	528.30	✓ 528.30
FRONT BUMPER SIDE BRACKET L/R <i>RH 2x</i>	2	52.30	35 104.60
FRONT RH BEARING <i>new</i>	1	192.50	+ 192.50
FRONT RH FENDER <i>Regis</i>	1	548.20	+ 548.20
FRONT RH FENDER INNER SHIELD <i>new</i>	1	92.40	+ 92.40
FRONT RH FENDER SIGNAL LAMP <i>crkhd</i>	1	148.60	✓ 148.60
Subtotal before discount			1,614.60
Percentage discount 25%			403.65
Sub-total 1			1,210.95
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00
FRONT RH 195/45R15 TYRE <i>new</i>	1	580.00	+ 580.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	+ 50.00
FRONT RH SPORT RIM <i>lit</i>	1	800.00	40 800.00
Subtotal before discount			1,510.00
Percentage discount 0%			0.00
Sub-total 2			1,510.00
Parts-total			2,720.95

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JODAN CHIN WEI LIANG
BLK 175 BISHAN ST 13 #05-163
SINGAPORE 570175

Contact : 96730468

ESTIMATE

Repair Code : CLM16370

Date in : 11/08/2020

Vehicle Num. : SBV3918T

Model : TOYOTA COROLLA 1.3M

Chassis/Eng# : EE1013032927/4E0495721

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 60.00

4 200.00

80 120.00

40 600.00

300 500.00

30 50.00

840

Labour Total

1,530.00

Parts & Labour Total

4,250.95

*** This is a computer-generated document which requires no signature.***

page 2

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin C
1/S 13/08/20

03 Days

total: 1803.92

1/S: 1-HIC ✓