

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20008315/KQF3E2

Date: 21/09/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS008914

Claimant Vehicle No : SHD9596Y

Insured Vehicle No : GBE491R

Date of Loss: 06/08/2020

Nature of Claim: TP Claim No: M2003845

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9596Y

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2C03566

Reg. Date: 29/03/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU903079598

Colour: Metallic Pearl White/Red

Odometer: 139767 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,263.80	4,209.80	14,054.00	76.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,170.00	890.00	6,280.00	87.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>25,433.80</b>	<b>5,099.80</b>	<b>20,334.00</b>	<b>79.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,780.37</b>	<b>356.99</b>	<b>1,423.38</b>	<b>79.95</b>
<b>Nett Amount (S\$)</b>	<b>27,214.17</b>	<b>5,456.79</b>	<b>21,757.38</b>	<b>79.95</b>

### INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 11/08/2020 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk  
(HQ)  
No 2 Ang Mo Kio St 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: SHIAU CHAN

Manager: KENNETH KONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2020)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9596Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Torn	516.00 FL	-	*516.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	82.30 FL	-	*82.30 FL
3	1		*COVER SUB-ASSY, ENGINE UNDER, NO.2	Serviceable	241.90 FL	-	*- FL
4	1		*EXTENSION, FRONT BUMPER, LH	Serviceable	120.10 FL	-	*- FL
5	1		*FRONT LED LAMP (LOWER) LH	Cracked	951.40 FL	-	*951.40 FL
6	1		*FRONT HEADLAMP LH	Cracked	2,637.60 FL	-	*2,637.60 FL
7	1		*COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	Serviceable	960.50 FL	-	*- FL
8	1		*MOTOR, HEADLAMP LEVELING, LH	Serviceable	487.50 FL	-	*- FL
9	1		*FRONT FENDER LH	Bent	977.80 FL	-	*977.80 FL
10	1		*LINER, FRONT FENDER, LH	Distorted	206.70 FL	-	*206.70 FL
11	1		*FRONT FENDER EMBLEM LH	Necessary	54.60 FL	-	*54.60 FL
12	1		*FRONT BONNET	Repair	983.10 FL	-	*- FL
13	1		*HINGE ASSY, HOOD, LH	Repair	58.90 FL	-	*- FL
14	1		*GRILLE, RADIATOR, LOWER NO.1	Serviceable	170.10 FL	-	*- FL
15	1		*SUPPORT, RADIATOR, UPPER LH	Serviceable	78.90 FL	-	*- FL
16	1		*HUB SUB-ASSY, FRONT AXLE, LH	Serviceable	668.90 FL	-	*- FL
17	1		*ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	Serviceable	760.10 FL	-	*- FL
18	1		*JOINT ASSY, LOWER BALL, FRONT LH	Serviceable	238.40 FL	-	*- FL
19	1		*KNUCKLE, STEERING, LH	Serviceable	663.40 FL	-	*- FL
20	1		*ABSORBER ASSY, SHOCK, FRONT LH	Serviceable	438.30 FL	-	*- FL
21	1		*SUPPORT SUB-ASSY, FRONT SUSPENSION, LH	Serviceable	236.40 FL	-	*- FL
22	1		*WIRE, ENGINE ROOM MAIN	Serviceable	7,323.90 FL	-	*- FL
23	1		*BATTERY	Serviceable	1,584.90 FL	-	*- FL
24	1		*CLAMP SUB-ASSY, BATTERY	Repair	115.50 FL	-	*- FL
25	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	-	*- FS
26	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	-	*- FS
27	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	-	*- FS
28	1		*SET CLIP, FRONT FENDER LINER	Necessary	65.00 FS	-	*65.00 FS
29	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	-	*- FS
30	1		*SET BUMPER CLIP FRT	Necessary	75.00 FS	-	*75.00 FS
31	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	65.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 23,403.10 5,566.40**  
**- List Item Discount on L Items 25.00/25.00% (\$\$) 5,139.30 1,356.60**

**Total Parts (\$\$) 18,263.80 4,209.80**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
Report was unsubmitted during this print-out.							

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	2,200.00	400.00
3	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
10	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
11	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING	New	380.00	0.00
12	TO DISMANTLE, TEST AND REFIT ELECTRICAL WIRING, FUSE BOX AND RELAY TO DIAGNOSE ELECTRICAL CONNECTION ISSUE	New	480.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,170.00</b>	<b>890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >