

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315 idac

Reg. No: 52983356E GST Reg. No. 20-0405911-H

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5947K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT NUMBER PLATE GARNISH	CUT	188.00	188.00
1	FRONT BUMPER COVER	DEFORMED	418.30	418.30
1	FRONT BUMPER SPONGE/ABSORBER	NOT NECESSARY	86.90	-
1	FRONT BUMPER BRACKET TOP (LH)	NOT NECESSARY	35.00	-
1	FRONT BUMPER BRACKET (LH)	NOT NECESSARY	28.00	-
1	FRONT BUMPER SIDE BRACKET SUPPORT	NOT NECESSARY	12.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT NUMBER PLATE GARNISH	REPEATED	188.00	-
1	RADIATOR GRILLE	NOT NECESSARY	1,409.10	-
1	UNIT ASSY-SMART CRU (RADAR SENSOR)	NOT NECESSARY	2,910.90	-
	LESS 20% DISCOUNT		-1,059.64	-121.26
			4,238.56	485.04
	NETT ITEMS			
1	FRONT NUMBER PLATE (N)	CRACKED	25.00	25.00
1	FRONT NO PLATE TRIM COVER (N)	СИТ	30.00	30.00
	LESS 10% DISCOUNT		-	-5.50
			55.00	49.50
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	320.00
	SPRAY PAINTING.		300.00	200.00
	WIRING CHARGE.		50.00	30.00
	DIAGNOSE/RESET-SMART CRU (RADAR SENSOR).	NOT NECESSARY	150.00	-
			-	-
			-	-
			900.00	550.00
	GRAND TOTAL		5,193.56	1,084.54
	RECOMMENDED COST OF REPAIRS			1,084.54

RECOMMENDED COST OF REPAIRS 1,084.54 (CONFIRMED)

Report Ref No. NS/INC20008316/T1vf3e2





Report Ref No. NS/INC20008316/T1vf3e2

**MOHAMAD TAUFIKH** 

fouring.

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser