

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20008327/EPA3Q2**Date:** 05/04/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMR3768A	Insured Vehicle No :	SHA7925K
Date of Loss:	09/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080148

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3768A	Engine No:	2ZR2F76904
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EUX0J051997
Reg. Date:	31/12/2019 (Man. Year: 2019)	Odometer:	54012 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,613.80	2,358.82	7,254.98	75.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	710.00	2,080.00	74.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,403.80	3,068.82	9,334.98	75.26
Approved Total (Overridden) (S\$)		2,450.00		
Nett Amount (S\$)	12,403.80	2,450.00	9,953.80	80.25
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,697.45		
Global Sum Settlement (S\$)		2,650.00		

INSPECTION

Date of Assignment:	12/08/2020	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK Singapore 408934
Date Inspected:	12/08/2020 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2020)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3768A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	570.00 FL	*570.00 FL
2	1		*FRONT BUMPER LOGO	Necessary	189.00 FL	*72.10 FL
3	1		*FRONT BUMPER FOGLAMP RH	Cut	435.00 FL	*435.00 FL
4	1		*FRONT BUMPER GRILLE (RH)	Cut	145.00 FL	*62.00 FL
5	1		*FRONT BUMPER GRILLE BASE	Cut	296.00 FL	*296.00 FL
6	1		*FRONT BUMPER TOP RUBBER	Not Necessary	48.00 FL	*- FL
7	1		*FRONT BUMPER TOP BEAM	Not Necessary	415.00 FL	*- FL
8	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	235.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	186.00 FL	*- FL
10	1		*FRONT BUMPER UNDER GARNISH	Not Necessary	298.00 FL	*- FL
11	2		*FRONT BUMPER SIDE RETAINER	Broken	118.00 FL	*118.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	459.00 FL	*- FL
13	1		*FRONT BUMPER TOWING COVER	Not Necessary	68.00 FL	*- FL
14	1		*FRONT BUMPER SPONGE	Not Necessary	119.00 FL	*- FL
15	1		*FRONT BUMPER LOWER	Not Necessary	415.00 FL	*- FL
16	1		*FRONT FENDER RH	Repair	985.00 FL	*- FL
17	1		*FRONT FENDER EMBLEM HYBRID	Necessary	65.00 FL	*65.00 FL
18	1		*FRONT FENDER INNER COWLING RH	Not Necessary	135.00 FL	*- FL
19	1		*FRONT FENDER GARNISH RH	Not Necessary	64.00 FL	*- FL
20	1		*HEADLAMP RH	Cut	1,487.00 FL	*1,487.00 FL
21	1		*FRONT SUPPORT PANEL	Not Necessary	468.00 FL	*- FL
22	1		*FRONT SUPPORT LOWER PANEL	Not Necessary	544.00 FL	*- FL
23	1		*FRONT SUPPORT TOP GARNISH	Not Necessary	289.00 FL	*- FL
24	1		*AIR GUARD RH	Not Necessary	71.00 FL	*- FL
25	1		*FRONT KNUCKLE ARM RH	Not Necessary	821.00 FL	*- FL
26	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	165.00 FL	*- FL
27	1		*FRONT SHOCK ABSORBER RH	Not Necessary	651.00 FL	*- FL
28	1		*FRONT LOWER ARM RH	Not Necessary	628.00 FL	*- FL
29	1		*STABILIZER LINK RH	Not Necessary	198.00 FL	*- FL
30	1		*STEERING ROD RH	Not Necessary	211.40 FL	*- FL
31	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*SET FRT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
33	1		*FRONT SPORTS RIM RH	Not Necessary	800.00 FS	*- FS
34	1		*FRONT TYRE RH	Not Necessary	250.00 FS	*- FS
35	1		*FRONT FENDER SEALANT RH	Not Necessary	150.00 FS	*- FS
36	1		*MISCELLANEOUS	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,308.40	3,135.10
- List Item Discount on L Items 25.00/25.00% (S\$)	2,694.60	776.28
Total Parts (S\$)	9,613.80	2,358.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
2	PANEL BEATING ON AFFECTED AREAS	New	800.00	250.00
3	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	450.00	0.00
5	REALIGN HEADLAMP	New	120.00	30.00
6	CHECK AND TEST FOR WATER LEAKAGE	New	50.00	0.00
7	CHECK AND RESET FAULT CODE LIGHT ON	New	250.00	0.00
8	CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (S\$)			2,790.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >