

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008331/QGA3Q2

**Date:** 27/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900088511

**Claimant**  
**Vehicle No :** SLB4299B **Insured Vehicle No :** SKP4818S

Date of Loss: 29/06/2020 Nature of Claim: TP Claim No: 1406125509SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLB4299B</b>		
Make & Model:	TOYOTA SIENTA, 1.5 X CVT (A)	Engine No:	2NR8553509
Reg. Date:	07/04/2016 (Man. Year: 2015)	Chassis No:	NSP1707012916
Colour:	Green	Odometer:	293853 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,409.50	1,106.25	1,303.25	54.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	980.00	640.00	39.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,029.50</b>	<b>2,086.25</b>	<b>1,943.25</b>	<b>48.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>(S\$)</b>	4,029.50	1,650.00	2,379.50	59.05
<b>+ GST 7.00/7.00% (S\$)</b>	282.07	115.50	166.57	59.05
<b>Nett Amount (S\$)</b>	<b>4,311.57</b>	<b>1,765.50</b>	<b>2,546.07</b>	<b>59.05</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,017.50</b>		

### INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)  
60 Jalan Lam Huat, #04-35/36 Carros  
Centre  
Singapore 737569

Estimated Period of Repair: 3.0 days

---

**Adjuster:** OI SUN PIN**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,879.00 FL	*1,120.00 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	432.00 FL	*- FL
3	1		*REAR TAILGATE TOYOTA LOGO	Necessary	60.00 FL	*60.00 FL
4	1		*REAR BUMPER CENTER PAD	Scratched	255.00 FL	*255.00 FL
5	1		*SET BUMPER CLIPS	Serviceable	80.00 FS	*- FS
6	1		*SET REVERSE SENSOR	Serviceable	260.00 FS	*- FS
7	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,066.00</b>	<b>1,465.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	656.50	358.75
<b>Total Parts (\$\$)</b>	<b>2,409.50</b>	<b>1,106.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE AND REAR BUMPER OUT TO FACILITATE REPLACEMENT OF PARTS	New	600.00	400.00
2	TO RESPRAY REAR BUMPER ,TAILGATE AND END PANEL	New	800.00	400.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	120.00
4	TRANSFER TAILGATE MECHANISM	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,620.00</b>	<b>980.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**