

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008334/GPA3Q2
Date: 05/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700015916-03
Claimant Vehicle No :	SMR7415S	Insured Vehicle No :	SKA3005G
Date of Loss:	07/08/2020	Nature of Claim:	TP
		Claim No:	3375167836SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR7415S		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5578841
Reg. Date:	20/01/2020 (Man. Year: 2009)	Chassis No:	RU11328801
Colour:	Grey	Odometer:	25119 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,362.40	1,030.00	1,332.40	56.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	400.00	400.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,162.40	1,430.00	1,732.40	54.78
Approved Total (Overridden) (S\$)		1,150.00		

(S\$)	3,162.40	1,150.00	2,012.40	63.64
+ GST 7.00/7.00% (S\$)	221.37	80.50	140.87	63.64
Nett Amount (S\$)	3,383.77	1,230.50	2,153.27	63.64
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,472.50		
Global Sum Settlement (S\$)		1,470.00		

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 17/08/2020

Estimated Period of Repair: 2.0 days

Inspected At: World Auto Pte Ltd - Kranji (HQ)
No 1 Kranji Loop
Singapore 739535

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	780.00 FL	*780.00 FL
2	1		*FRONT BUMPER SIDE RETAINER L/H	Not Necessary	45.00 FL	*- FL
3	1		*FRONT GRILLE BASE	Cut	420.00 FL	*420.00 FL
4	1		*HEADLAMP ASSY LH	Not Necessary	1,450.00 FL	*- FL
5	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	78.00 FL	*- FL
6	1		*FOG LAMP GARNISH LH	Not Necessary	80.00 FL	*- FL
7	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
8	1		*FRONT NUMBER PLATE WITH CASING	Scratched	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,933.00	1,270.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	570.60	240.00
Total Parts (\$\$)	2,362.40	1,030.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT AND STRAIGHTEN FRONT SUPPORT PANEL WHERE NECESSARY ,AND REPLACE ABOVE PART	New	400.00	200.00
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	New	400.00	200.00
Gross Labour Cost (\$\$)			800.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >