# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008335/KCF3Q2

11/02/2021 Date:

**REFERENCE** 

China Taiping Insurance (Singapore) Handling Insurer:

Pte. Ltd.

Policy No: DMHCSNA00000381900

**Claimant Vehicle** 

GBD1763E

**Insured Vehicle** No:

SKZ3426T

Date of Loss:

No:

07/08/2020

Nature of Claim: TP Claim No:

SNM20D202792/C02/TKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBD1763E** 

NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M) Make & Model:

Engine No: YD25350827A

Reg. Date: 17/07/2014 (Man. Year: 2014) Chassis No: Odometer:

JN1MC2E26Z0002332 160245 km

Colour: Silver 2488 cc

**Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

**CONDITION OF TYRES** 

Rear Tyre Size: Front Tyre Size: 195R15X8 195R15X8 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 6 mm Front Right Side: Michelin 7 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,570.39	1,570.39	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	640.00	120.00	15.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,330.39	2,210.39	120.00	5.15
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	2,330.39	2,000.00	330.39	14.18
+ GST 7.00/7.00% (S\$)	163.13	140.00	23.13	14.18
Nett Amount (S\$)	2,493.52	2,140.00	353.52	14.18

INSPECTION

Date Inspected:

Date of Assignment: 12/08/2020

> 13/08/2020 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)

160 Sin Ming Drive #02-20, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: **CELINE FONG** 

NOTE: This report represents our findings at the tany other liability under any other circumstances i	ime and place of inspection stated herein s hereby expressly excluded.	. Such inspection has been carried out to	the best of our knowledge and ability but

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

### **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 05 Feb 2021)

Parts: N/A NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBD1763E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	514.70 FN	*514.70 FN
2	1		*N/S FRONT BUMPER SIDE RETAINER	Cracked	161.70 FN	*161.70 FN
3	8		*FRONT BUMPER CLIPS	Necessary	40.80 FN	*40.80 FN
4	1		*N/S FRONT BUMPER FOG COVER	Cracked	107.50 FN	*107.50 FN
5	1		*N/S FRONT BUMPER FOG LAMP	Mtg Cracked	311.80 FN	*311.80 FN
6	1		*N/S HEADLAMP ASSY	Mtg Cracked	366.10 FN	*366.10 FN
7	1		*N/S FRONT DOOR STEP GARNISH	Dented/Cracked	214.50 FN	*214.50 FN
8	1		*N/S FRONT DOOR ROC STICKER	Necessary	25.00 FS	*25.00 FS
F=Fra	nchise	part. S=SpcNe	ett. N=NettItemDisc.	_		
				Sub Total (S\$)	1,742.10	1,742.10
			- Nett Item Discount	on N Items 10.00/10.00% (S\$)	171.71	171.71
				Total Parts (S\$)	1,570.39	1,570.39
			Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	280.00	220.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	450.00	400.00
3	TO FOCUS HEADLAMPS.TO CHECK FRONT WIRING AND LIGHTING OPERATION	New	30.00	20.00
	Gross Labo	ur Cost (S\$)	760.00	640.00
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >