Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008335/KCF3Q2

Date: 09/02/2021

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMHCSNA00000381900

Claimant Vehicle No:

GBD1763E

Insured Vehicle No:

SKZ3426T

Date of Loss: 07/08/2020 Nature of TP Claim SNM20D202792/C02/TKL No:

JN1MC2E26Z0002332

Claim:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**GBD1763E** Reg No:

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)

Engine No: YD25350827A

Reg. Date: 17/07/2014 (Man. Year: 2014)

Odometer: 160245 km

Chassis No:

Colour: Silver **Engine Capacity:** 2488 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

**CONDITION OF TYRES** 

Front Tyre Size: 195R15X8 Rear Tyre Size: 195R15X8 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 7 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,570.39	1,570.39	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	640.00	120.00	15.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,330.39	2,210.39	120.00	5.15
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	2,330.39	2,000.00	330.39	14.18
+ GST 7.00/7.00% (S\$)	163.13	140.00	23.13	14.18
Nett Amount (S\$)	2,493.52	2,140.00	353.52	14.18

**INSPECTION** 

Date of Assignment: 12/08/2020

Date Inspected: 13/08/2020 Inspected At: K Kim Hin Auto Pte Ltd (HQ)

160 Sin Ming Drive #02-20, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: CELINE FONG Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference					
Part Source:		(Last Synchronised: 05 Feb 2021)			
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	: (Unsubmitted, no print-code for GBD1763E)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

# **Recommended Parts**

Qty	Part No.	Particulars	Condition	Repairer's	Amount
		*FRONT BUMPER	Bent	514.70 FN	*514.70 FN
		*N/S FRONT BUMPER SIDE RETAINER	Cracked	161.70 FN	*161.70 FN
		*FRONT BUMPER CLIPS	Necessary	40.80 FN	*40.80 FN
		*N/S FRONT BUMPER FOG COVER	Cracked	107.50 FN	*107.50 FN
		*N/S FRONT BUMPER FOG LAMP	Mtg Cracked	311.80 FN	*311.80 FN
		*N/S HEADLAMP ASSY	Mtg Cracked	366.10 FN	*366.10 FN
		*N/S FRONT DOOR STEP GARNISH	Dented/Cracked	214.50 FN	*214.50 FN
		*N/S FRONT DOOR ROC STICKER	Necessary	25.00 FS	*25.00 FS
hise	part. S=SpcN	Nett. N=NettItemDisc.			
			Sub Total (S\$)	1,742.10	1,742.10
		- Nett Item Discount on N Items	s 10.00/10.00% (S\$)	171.71	171.71
			Total Parts (S\$)	1,570.39	1,570.39
3			*N/S FRONT BUMPER SIDE RETAINER  *FRONT BUMPER CLIPS  *N/S FRONT BUMPER FOG COVER  *N/S FRONT BUMPER FOG LAMP  *N/S HEADLAMP ASSY  *N/S FRONT DOOR STEP GARNISH  *N/S FRONT DOOR ROC STICKER  nise part. S=SpcNett. N=NettItemDisc.	*FRONT BUMPER SIDE RETAINER Cracked  *N/S FRONT BUMPER CLIPS Necessary  *N/S FRONT BUMPER FOG COVER Cracked  *N/S FRONT BUMPER FOG LAMP Mtg Cracked  *N/S HEADLAMP ASSY Mtg Cracked  *N/S FRONT DOOR STEP GARNISH Dented/Cracked  *N/S FRONT DOOR ROC STICKER Necessary  nise part. S=SpcNett. N=NettItemDisc.  Sub Total (S\$)  - Nett Item Discount on N Items 10.00/10.00% (S\$)	*FRONT BUMPER SIDE RETAINER Cracked 161.70 FN *N/S FRONT BUMPER SIDE RETAINER Cracked 161.70 FN  *FRONT BUMPER CLIPS Necessary 40.80 FN *N/S FRONT BUMPER FOG COVER Cracked 107.50 FN  *N/S FRONT BUMPER FOG LAMP Mtg Cracked 311.80 FN *N/S HEADLAMP ASSY Mtg Cracked 366.10 FN  *N/S FRONT DOOR STEP GARNISH Dented/Cracked 214.50 FN *N/S FRONT DOOR ROC STICKER Necessary 25.00 FS  nise part. S=SpcNett. N=NettItemDisc.  Sub Total (\$\$) 1,742.10  - Nett Item Discount on N Items 10.00/10.00% (\$\$) 171.71

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	280.00	220.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	450.00	400.00
3	TO FOCUS HEADLAMPS.TO CHECK FRONT WIRING AND LIGHTING OPERATION	New	30.00	20.00
	Gross Labou	r Cost (S\$)	760.00	640.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >