

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008337/EPS3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700038106
Claimant Vehicle No :	SMD3160B	Insured Vehicle No :	SLR4455H
Date of Loss:	12/08/2020	Nature of Claim:	TP
		Claim No:	3994583928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD3160B	Engine No:	HR12193484J
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Chassis No:	JN1TAAE12Z0982020
Reg. Date:	14/08/2018 (Man. Year: 2018)	Odometer:	27598 km
Colour:	Yellow		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/50 R15	Rear Tyre Size:	185/50 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,749.12	9,811.13	5,937.99	37.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	3,610.00	1,490.00	29.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,849.12	13,421.13	7,427.99	35.63
+ GST 7.00/7.00% (S\$)	1,459.44	939.48	519.96	35.63
Nett Amount (S\$)	22,308.56	14,360.61	7,947.95	35.63
+ Loss of Use (16.0 x S\$60.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		15,322.61		
Global Sum Settlement (S\$)		15,320.00		

INSPECTION

Date of Assignment:	12/08/2020		
Date Inspected:	13/08/2020	Inspected At:	Ryder Auto Workshop LLP (HQ) 1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	14.0 days		

4/12/2021

Adjuster Report

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	681.40 FN	*520.00 FN
2	10		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
3	1		*REAR BUMPER SPONGE	Broken	210.00 FN	*135.00 FN
4	2		*REAR BUMPER SCREW CLIPS	Necessary	20.00 FS	*10.00 FS
5	2		*REAR BUMPER O/S & N/S REFLECTOR	Broken	244.20 FN	*152.00 FN
6	2		*REAR BUMPER O/S & N/S RETAINER (INNER)	Broken	190.60 FN	*120.00 FN
7	2		*REAR BUMPER O/S & N/S RETAINER (OUTER)	Bent	210.20 FN	*210.20 FN
8	1		*REAR BUZZEL	Broken	265.40 FN	*225.00 FN
9	1		*REAR REVERSE SENSOR	Broken	280.00 FS	*200.00 FS
10	1		*REAR END PANEL	Dented	681.90 FN	*552.00 FN
11	1		*REAR END PANEL INNER TRIM	Crushed	183.50 FN	*105.00 FN
12	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	16.00 FS	*10.00 FS
13	2		*REAR O/S & N/S TAIL-LAMP	Broken	1,178.20 FN	*870.00 FN
14	2		*REAR O/S & N/S TAIL-LAMP PANEL	Dented	663.80 FN	*370.00 FN
15	1		*REAR REGN NO. PLATE LAMP	Not Necessary	167.50 FN	*- FN
16	1		*REAR BOOT COVER	Dented	1,474.40 FN	*1,126.00 FN
17	1		*REAR BOOT COVER WEATHERSTRIP	Crushed	240.50 FN	*160.00 FN
18	1		*REAR BOOT COVER NOTE EMBLEM	Necessary	71.70 FN	*71.70 FN
19	1		*REAR BOOT COVER INNER TRIM	Broken	356.60 FN	*356.60 FN
20	1		*REAR BOOT COVER INNER TRIM CLIPS (11 PCS)	Necessary	44.00 FS	*15.00 FS
21	2		*REAR BOOT COVER O/S & N/S HINGES	Not Necessary	160.00 FN	*- FN
22	1		*REAR BOOT COVER MOULDING	Not Necessary	287.10 FN	*- FN
23	4		*REAR BOOT COVER MOULDING CLIPS	Not Necessary	16.00 FS	*- FS
24	1		*REAR BOOT COVER LOCK(UPPER)	Bent	291.60 FN	*213.00 FN
25	1		*REAR BOOT COVER LOCK(LOWER)	Not Necessary	43.10 FN	*- FN
26	1		*REAR BOOT FLOOR PANEL	Dented	1,318.75 FN	*891.00 FN
27	1		*REAR BOOT FLOOR PANEL INSULATOR	Necessary	336.96 FS	*200.00 FS
28	2		*REAR BOOT FLOOR O/S & N/S CORNER PANEL	Repair	463.80 FN	*- FN
29	1		*REAR N/S CHASSIS FRAME	Dented	355.20 FN	*355.20 FN
30	1		*REAR N/S FENDER (NPA)	Repair	0.00 FN	*- FN
31	1		*REAR N/S FENDER (NPA)WHEEL GUARD	Torn	163.80 FN	*163.80 FN
32	6		*REAR N/S FENDER (NPA)WHEEL GUARD CLIPS	Necessary	24.00 FS	*15.00 FS
33	1		*REAR N/S FENDER INNER TRIM	Deformed	423.20 FN	*398.00 FN
34	1		*REAR N/S FENDER INNER TRIM CLIPS (8 PCS)	Necessary	32.00 FS	*15.00 FS
35	1		*REAR N/S FENDER AIR VENT	Broken	165.60 FN	*55.00 FN
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
37	1		*REAR WINDSCREEN INNER SEAL	Necessary	160.00 FN	*80.00 FN
38	1		*REAR REGN NO PLATE	Cut	45.00 FS	*40.00 FS
39	1		*REAR REGN NO PLATE BRACKET	Not Necessary	29.00 FS	*- FS
40	1		*FRONT BUMPER	Broken	796.70 FN	*394.00 FN
41	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
42	1		*FRONT BUMPER ENFORCEMENT	Not Necessary	596.70 FN	*- FN
43	1		*FRONT BUMPER N/S RETAINER	Broken	86.70 FN	*86.70 FN
44	1		*FRONT BUMPER TOP GARNISH	Broken	213.20 FN	*194.00 FN
45	1		*FRONT GRILLE EMBLEM	Necessary	91.70 FN	*70.00 FN
46	1		*FRONT GRILLE CLIPS (6 PCS)	Necessary	24.00 FS	*10.00 FS
47	1		*FRONT N/S HEAD-LAMP	Broken	896.80 FN	*796.00 FN
48	1		*FRONT N/S SUPPORT PANEL GARNISH	Deformed	86.50 FN	*68.00 FN
49	1		*FRONT N/S CHASSIS (OUTER PORTION)	Dented	210.20 FN	*210.20 FN

Report was unsubmitted during this print-out.

4/12/2021

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRONT N/S CHASSIS (OUTER PORTION)BRACKET	Dented	265.00 FN	*180.00 FN
51	1		*REAR O/S FENDER INNER TRIM	Deformed	423.20 FN	*398.00 FN
52	1		*REAR BOOT FLOOR PANEL	Repeated	880.60 FN	*- FN
53	1		*REAR SPARE TYRE SPONGE	Broken	285.60 FN	*170.00 FN
54	1		*REAR BOOT COVER HANDLE	Broken	96.50 FN	*96.50 FN
55	1		*REAR BOOT COVER EMBLEM	Necessary	81.60 FN	*81.60 FN
56	1		*FRONT GRILLE BASE }	Broken	321.20 FN	*321.20 FN
57	1		*FRONT GRILLE CHROME }		362.60 FN	*- FN
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					17,383.81	10,830.70
- Nett Item Discount on N Items 10.00/10.00% (S\$)					1,634.69	1,019.57
Total Parts (S\$)					15,749.12	9,811.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,STRAIGHTEN ,WELDING & REPLACE FRONT DAMAGE PARTS	New	400.00	200.00
2	TO SPRAY PAINT FRONT DAMAGE PARTS	New	400.00	200.00
3	TO DISMANTLE ,STRAIGHTEN ,WELDING & REPLACE REAR DAMAGE PARTS	New	1,600.00	1,400.00
4	TO SPRAY PAINTING	New	1,400.00	1,400.00
5	TO RE-ALIGN REAR N/S CHASSIS	New	200.00	100.00
6	TO REMOVE & REFIT REAR SEAT ,ROOF LINING	New	160.00	80.00
7	TO REMOVE & REPLACE REAR WINDSCREEN	New	160.00	120.00
8	TO CHECK WIRING	New	100.00	30.00
9	TO RE-SEAL ELECTRICAL SYSTEM	New	480.00	30.00
10	TO RE-SEAL ANTI-RUST	New	200.00	50.00
Gross Labour Cost (S\$)			5,100.00	3,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >