Page 1 of 5 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20008343/KTF3E2

Date: 31/08/2020

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: ML000126 Claimant Vehicle SHD81A

Insured Vehicle No: SLQ3891T No:

Nature of Claim: TP Date of Loss: 10/08/2020 Claim No: M2003897

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD81A

Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C003114 Reg. Date: 24/07/2017 (Man. Year: 2016) Chassis No: VF1ABL15AUC283395

Colour: Metallic White/Red Odometer: 344461 km

**Engine Capacity:** 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: Rear Tyre Size: 215/60 R16 215/60 R16 Front Left Side: Rear Left Side: Sailun 9 mm Sailun 9 mm Rear Right Side: Front Right Side: Sailun 9 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,291.41	1,056.24	6,235.17	85.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	490.00	5,370.00	91.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,151.41	1,546.24	11,605.17	88.24
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	13,151.41	1,250.00	11,901.41	90.50
+ GST 7.00/7.00% (S\$)	920.60	87.50	833.10	90.50
Nett Amount (S\$)	14,072.01	1,337.50	12,734.51	90.50

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 12/08/2020 Inspected At: Trans Cab Auto Services Pte Ltd - Amk

(HQ)

No 2 Ana Mo Kio St 63 Singapore 569111

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

# **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Aug 2020)

Parts: RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0) 143

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SHD81A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
1	1	*BUMPER COVER REAR	Cracked	561.70 FL	-	*561.70 FL
2	1	*BUMPER LOWER REAR	Dented / Cut	411.90 FL	-	*411.90 FL
3	1	*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*- FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*- FL
6	1	*BUMPER REFLECTOR REAR	Serviceable	16.60 FL	-	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
9	1	*BUMPER BEAM REAR	Repair	547.80 FL	-	*- FL
10	1	*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	-	*- FL
11	1	*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	-	*- FL
12	1	*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	-	*- FL
13	1	*OUTER PANEL REAR (END PANEL) TR	IM Serviceable	404.56 FL	-	*- FL
14	1	*TAIL-LAMP	Serviceable	401.40 FL	-	*- FL
15	1	*BOOT REAR	Repair	1,677.20 FL	-	*- FL
16	1	*BOOT WEATHERSTRIP	Serviceable	178.20 FL	-	*- FL
17	1	*BOOT REFLECTOR LAMP	Serviceable	277.70 FL	-	*- FL
18	1	*BOOT BADGE RENAULT	Not Necessary	82.40 FL	-	*- FL
19	1	*BOOT BADGE	Not Necessary	95.80 FL	-	*- FL
20	1	*EXHAUST CAP REAR	Serviceable	125.40 FL	-	*- FL
21	1	*SET PARKING AID	Serviceable	700.00 FS	-	*-FS
22	1	*SET REAR BUMPER CLIP	Necessary	75.00 FS	-	*75.00 FS
23	1	*SET BUMPER BRACKET CTR CLIP	Not Necessary	55.00 FS	-	*-FS
24	1	*SET BUMPER BRACKET SIDE CLIP RH	RR Not Necessary	60.00 FS	-	*-FS
25	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	65.00 FS	-	*-FS
26	1	*SET BUMPER BRACKET SIDE CLIP LH	RR Not Necessary	60.00 FS	-	*-FS
27	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	65.00 FS	-	*-FS
28	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	69.00 FS	-	*-FS
29	1	*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	-	*75.00 FS
30	1	*BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	-	*-FS
31	1	*BOOT STICKER 6555-3333	Not Necessary		-	*-FS
32	1	*TAILLAMP CLIP	Not Necessary	45.00 FS	-	*-FS
33	1	*REAR BUMPER PROTECTOR	Necessary	170.00 FS	_	*30.00 FS
34	1	*REAR LICENCE PLATE WITH HOLDER	Serviceable	120.00 FS	-	*- FS
35	1	*REAR END PANEL TRIM CLIP	Not Necessary	55.00 FS	_	*- FS
F=Fra	anchise	part. S=SpcNett. L=ListItemDisc.				

1,153.60 **Sub Total (S\$)** 7,904.46 - List Item Discount on L Items 10.00/10.00% (S\$) 97.36 613.05

> **Total Parts (S\$)** 7,291.41

1.056.24

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No. Qty Part No. Particulars	Condition	Repairer's	Reference	Amount
Report was unsubmitted dur	ing this print-out.			7

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
3	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
6	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	220.00
8	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
10	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
	Gross Labour Cost (S\$)		5,860.00	490.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >