

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20008349/Aea3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	17/06/2021	
	ATTN:PETER			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKB 7746U	Veh. Inspected	k	SFD 89C	
	Policy No.	GA509962	Coverage (\$)		0.00	
	Claim No.	S0M02QKO	Excess (\$)		0.00	
	Assign From		Assign Date		12/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA STREAM	c.c		1799	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	RN61064334	Colour		SILVER	
	Odometer	255840 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	WEST LAKE		6 mm	
	L/H Front Tyre	215/45 R17	WEST LAKE		6 mm	
	R/H Rear Tyre	215/45 R17	PIRELLI		6 mm	
	L/H Rear Tyre	215/45 R17	PIRELLI		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	09/07/2020	Inspection Dat	e	12/08/2020	
	Survey held at	MG SOLUTION PTE LTD	•			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				