

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III20008359/UVF3E2

Date: 25/08/2020

REFERENCE

Insured/Claimant:	SEAH GEK LI, TRACY	Policy No:	D20MPC0000545	
Date of Loss:	12/08/2020	Nature of Claim:	OD	Claim No: MPC2020D0001520

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3009T			
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)		Engine No:	K24W72400308
Reg. Date:	06/02/2018 (Man. Year: 2017)		Chassis No:	JHMRC1890JC200733
Colour:	Red		Odometer:	34201 km
Engine Capacity:	2356 cc			
Market Value/New Car Price:	S\$105,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,971.44	1,220.48	750.96	38.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	830.00	1,220.00	59.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,021.44	2,050.48	1,970.96	49.01
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (S\$)	3,021.44	1,050.48	1,970.96	65.23

INSPECTION

Date of Assignment:	13/08/2020		
Date Inspected:	13/08/2020	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2020)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EXV-S CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW3009T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S DOOR SIDE MIRROR	Cracked	1,361.90 FL	*1,361.90 FL
2	1		*FRONT N/S DOOR SIDE MIRROR CASE	Cracked	77.80 FL	*77.80 FL
3	1		*SET FRONT N/S DOOR FRAME STICKER	Not Necessary	107.60 FL	*- FL
4	1		*FRONT N/S DOOR GLASS	Serviceable	574.90 FL	*- FL
5	1		*FRONT N/S DOOR GLASS OUTER MOULDING	Dented	85.90 FL	*85.90 FL
6	1		*FRONT N/S QUARTER GLASS MOULDING	Not Necessary	112.20 FL	*- FL
7	1		*FRONT N/S QUARTER GLASS SEALANT	Not Necessary	60.00 FL	*- FL
8	15		*FRONT N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	84.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,464.30	1,525.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	492.86	305.12
Total Parts (\$\$)	1,971.44	1,220.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX FRONT N/S DOOR INNER TRIM BOARD COVER, DOOR GLASS, REGULATOR, MOTOR, CHANNEL & NECESSARY PARTS	New	150.00	60.00
3	TO REMOVE & REFIX FRONT N/S QUARTER GLASS & MOULDING	New	150.00	0.00
4	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT N/S FENDER, FRONT N/S DOOR & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	750.00	300.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	950.00	450.00
Gross Labour Cost (S\$)			2,050.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >