



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20008362/Bcf3e2	Date: 15/06/2021
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJR 5493P	Veh. Inspected	GBH 5853G
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10006987	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	13/08/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE TURBO	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFHT02P200243997	Colour	SILVER
	Odometer	91868 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	POOR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15	HANKOOK	6 mm
	L/H Front Tyre	195 R15	HANKOOK	6 mm
	R/H Rear Tyre	195 R15	HANKOOK	6 mm
	L/H Rear Tyre	195 R15	HANKOOK	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	12/08/2020	Inspection Date	13/08/2020
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	