

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008363/UPA3Q2

Date: 22/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900246703

Claimant
Vehicle No : SLP1185S **Insured Vehicle No :** SBW1788J

Date of Loss: 07/08/2020 Nature of Claim: TP Claim No: 0011949205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1185S		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B3538533
Reg. Date:	26/05/2017 (Man. Year: 2016)	Chassis No:	GK81007286
Colour:	Silver	Odometer:	50850 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50Z R16	Rear Tyre Size:	205/50Z R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,650.32	840.00	1,810.32	68.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	440.00	1,140.00	72.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,230.32	1,280.00	2,950.32	69.74
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	4,230.32	1,000.00	3,230.32	76.36
+ GST 7.00/7.00% (S\$)	296.12	70.00	226.12	76.36
Nett Amount (S\$)	4,526.44	1,070.00	3,456.44	76.36
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,286.00		

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 13/08/2020 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Warped	1,050.00 FL	*1,050.00 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Not Necessary	25.40 FL	*- FL
3	1		*O/S HEADLAMP	Not Necessary	2,050.00 FL	*- FL
4	1		*FRONT BUMPER PARKING SENSOR	Not Necessary	150.00 FS	*- FS
					Sub Total (S\$)	3,275.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	625.08
					Total Parts (S\$)	2,650.32
						840.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
2	TO REINSTALL OF FRONT BUMPER PARKING SENSOR	New	80.00	40.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	450.00	180.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	450.00	200.00
5	TO REDO PAINT COATING	New	550.00	0.00
Gross Labour Cost (\$\$)			1,580.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >