



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SBW1788J

Date of Accident : 07 August 2020

Mr Teo Hee Lye, Jason (Zhang Xilai)

Date : 11 August 2020

LKK - Marcus

13/08/2020 C09CWH

Estimate To Repair SLP1185S - Honda SHUTTLE 1.5G CVT

Chassis No : GK81007286

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>de/wornd</i>	\$ 1,050.00
02	1 pc	front bumper side retainer o/s <i>11</i>	\$ 25.40
03	1 pc	o/s headlamp <i>11</i>	\$ 2,050.00
			\$ 3,125.40
		Less 20 %	\$ 625.08
			\$ 2,500.32
		<u>SPECIAL NETT ITEMS</u>	
04	1 pc	front bumper parking sensor <i>11</i>	\$ 150.00
			\$ 150.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 50.00
02		To reinstall of front bumper parking sensor.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450.00
04		Putty and spray painting of the affected portion.	\$ 450.00
05		To redo paint coating.	\$ <i>11</i> 550.00
			\$ 1,580.00
		Total	\$ 4,230.32

*not Authorized
LKK
2/5 \$ 1000
2 days.
Take photo. After my
13/8/20*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1420008363/UK93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / W / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLP11855

at Workshop m/s

Tanhm 9m

of

Insured:

SBW1788J

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$55k.

IDAC Accident Rpt:

Consistent? : Yes or No

SL / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5056

Date:

Person Contacted:

LTA 41327

Vehicle: IN / OUT

Date / Time

Action / Instruction

have vides at folder

7/10/20 confirmed 2/5 \$1000 with mr Tan

Veh No:

SLP11855

Yr Regn:

5/17

Type: M / M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Honda shuttle

C.C

1496

Colour

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

50850

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK81007286

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50ZR16

R:

BS / DUN / EXNOVA / GY / FS / LIZA MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/8/20

D.O.I.

13/8/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 fnt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL