

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4163X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DEFORMED	418.30	418.30
1	FRONT BUMPER BRACKET RH	NOT NECESSARY	28.00	-
1	FRONT RADIATOR GRILLE MOULDING UPP	TO REPAIR SEE LABOUR	48.30	-
1	FRONT RADIATOR GRILLE	NOT NECESSARY	1,409.10	-
1	FRONT FENDER RH BLUE DRIVE	NECESSARY	26.60	26.60
1	HEAD LAMP RH	NOT NECESSARY	1,993.65	-
1	BUMPER GRILLE RH	NOT NECESSARY	85.10	-
	LESS 20% DISCOUNT		-801.81	-88.98
			3,207.24	355.92
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
			50.00	-
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT RADIATOR GRILLE MOULDING UPP.		570.00	320.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
			1,190.00	750.00
	GRAND TOTAL		4,447.24	1,105.92
	RECOMMENDED COST OF REPAIRS			1,105.92

Report Ref No. NS/INC20008364/T1sf3s2

MOHAMAD TAUFIKH

(CONFIRMED)

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.