



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3203L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	1,052.20	1,052.20
1	FRT BUMPER UPR BRKT RH	NOT NECESSARY	22.40	-
1	FRT BUMPER SIDE BRKT RH	NOT NECESSARY	24.60	-
1	FRT FENDER RH	BENT	663.00	663.00
1	FRT FENDER SHIELD RH	DEFORMED	174.90	174.90
1	HEADLAMP RH	CUT	1,388.00	1,388.00
1	FRT WHEEL CAP RH	DEFORMED	107.10	107.10
	LESS 20% DISCOUNT		-686.44	-677.04
			2,745.76	2,708.16
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	420.00
	SPRAY PAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.		40.00	30.00
	WHEEL ALIGNMENT.		120.00	80.00
			1,300.00	960.00
	GRAND TOTAL		4,045.76	3,668.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,950.00

Report Ref No. NS/INC20008365/T1sf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.