

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4254H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	(I40) FRT DOOR LOGO SONATA (N)	CUT	75.00	75.00
	LESS 10% DISCOUNT		-7.50	-7.50
			67.50	67.50
	<u>LABOUR</u>			
	PANEL BEATING.		300.00	200.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
			550.00	400.00
	GRAND TOTAL		617.50	467.50

RECOMMENDED COST OF LUMP SUM REPAIRS		350.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC20008366/T1qf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.