

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







| NTUC INCOME INSURANCE CO-OPERATIVE LTD                                 |   |   | Ref:          | NS/INC20008366/T1qf3e2 |            |  |
|--|---|---|---------------|------------------------|------------|--|
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |   |   | Date:         | 21-08-2020<br>INC4     |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |   |   |               |                        |            |  |
|  | Insured Veh.  | SMM 4754J                                 | Veh. Ir       | nspected               | SHA 4254H  |  |
|  | Policy No.  | 5111131291                                | Coverage (\$) |                        | 0.00       |  |
|  | Claim No.   | MT/1100550-001                            | Exces         | s (\$)                 | 0.00       |  |
|  | Assign From   |   | Assig         | n Date                 | 12/08/2020 |  |
| 2. Vehicle Particulars & Condition                                     |   |   |               |                        |            |  |
|  | Make & Model  | HYUNDAI 140                               | c.c           |                        | 1685       |  |
|  | Engine No.  | HIDDEN                                    | Year o        | f Reg.                 | 2016       |  |
|  | Chassis No.   | KMHLB41UMHU096602                         | Colou         | r                      | BLUE       |  |
|  | Odometer  | 535174                                    | Steering      |                        | IN ORDER   |  |
|  | Brakes  | IN ORDER                                  | Modifi        | cation                 | SPORTS RIM |  |
|  | General   | GOOD                                      |               |                        |            |  |
| 3. Conditions of Tyres   |   |   |               |                        |            |  |
|  |   | Size                                      | Make          |                        | Balance    |  |
|  | R/H Front Tyre  | 205/60 R16                                | HANKC         | OOK                    | 6 mm       |  |
|  | L/H Front Tyre  | 205/60 R16                                | HANKO         |                        | 6 mm       |  |
|  | R/H Rear Tyre   | 205/60 R16                                | HANKO         |                        | 6 mm       |  |
|  | L/H Rear Tyre   | 205/60 R16                                | HANKC         |                        | 6 mm       |  |
| 4.   | <u> </u>  |   |               |                        |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  |   |               |                        |            |  |
|  | DAMAGES SEE DETAILS.  |   |               |                        |            |  |
| 5.   | General Information   |   |               |                        |            |  |
|  | Accident Date   | 05/08/2020                                | Inspec        | tion Date              | 12/08/2020 |  |
|  | Survey held at  | held at COMFORTDELGRO ENGINEERING PTE LTD |               |                        |            |  |
|  |   | 59 LOYANG DRIVE<br>SINGAPORE 508969       |               |                        |            |  |
| 5a.  | a. Remarks  |   |               |                        |            |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |               |                        |            |  |
| 5b.  | 5b. Estimate Days of Repair   |   |               |                        |            |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days  |   |               |                        |            |  |