

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008369/KQF3Q2

Date: 04/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00025812001

**Claimant
Vehicle No :** SCY332A

**Insured
Vehicle No :** SMJ199D

Date of Loss: 07/08/2020

Nature of
Claim: TP

Claim
No: SNM20D202769C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCY332A**

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A)

Engine No: R16B25502266

Reg. Date: 27/12/2018 (Man. Year: 2018)

Chassis No: MRHFC5650JT001984

Colour: Metallic Dark Blue

Odometer: 20871 km

Engine Capacity: 1597 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: VENUS 7 mm

Rear Left Side: Hankook 8 mm

Front Right Side: VENUS 7 mm

Rear Right Side: Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,423.48	9,506.31	2,917.17	23.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	3,310.00	2,030.00	38.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,763.48	12,816.31	4,947.17	27.85
+ GST 7.00/7.00% (S\$)	1,243.44	897.14	346.30	27.85
Nett Amount (S\$)	19,006.92	13,713.45	5,293.47	27.85

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 13/08/2020 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCY332A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Bent	531.20 FL	*531.20 FL
2	1		*BOOT OUTER GARNISH	Mtg Cracked	110.90 FL	*110.90 FL
3	1		*BOOT EMBLEM	Necessary	138.00 FL	*138.00 FL
4	1		*BOOT BADGE CIVIC	Necessary	21.50 FL	*21.50 FL
5	1		*BOOT BADGE IVTEC	Necessary	20.60 FL	*20.60 FL
6	1		*BOOT WEATHERSTRIP	Distorted	70.40 FL	*70.40 FL
7	15		*BOOT TRIM BOARD CLIPS	Necessary	52.50 FL	*52.50 FL
8	1		*BOOT LOCK	Dented	81.20 FL	*81.20 FL
9	1		*BOOT STOPPER LH	Missing	9.50 FL	*9.50 FL
10	1		*REAR BUMPER	Buckled / Cracked	617.50 FL	*556.44 FL
11	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
12	1		*REAR BUMPER BRACKET LH	Repair	12.40 FL	*- FL
13	1		*REAR BUMPER TOP RETAINER LH	Distorted	25.40 FL	*25.40 FL
14	1		*REAR BUMPER CENTER DIFFUSER COVER	Cracked	260.30 FL	*260.30 FL
15	1		*REAR BUMPER TOW POINT COVER	Dented	18.70 FL	*18.70 FL
16	1		*REAR BUMPER REFLECTOR LH	Serviceable	17.20 FL	*- FL
17	1		*REAR BUMPER REFLECTOR COVER	Dented	25.40 FL	*25.40 FL
18	2		*REAR BUMPER REVERSE SENSORS	Missing / Dented	267.80 FL	*267.80 FL
19	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	228.80 FL	*228.80 FL
20	1		*REAR BUMPER REVERSE SENSOR WIRING HARNESS	Cut	135.00 FL	*135.00 FL
21	1		*REAR BUMPER INNER BOOT SENSOR	Cracked	58.10 FL	*58.10 FL
22	1		*REAR BUMPER INNER BOOT SENSOR BUZZER	Cracked	80.20 FL	*80.20 FL
23	1		*REAR BUMPER CORNER RETAINER	Distorted	25.40 FL	*25.40 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	160.40 FL	*160.40 FL
25	1		*TAILLAMP LH	Cracked	285.40 FL	*285.40 FL
26	1		*TAILLAMP GASKET	Necessary	25.00 FL	*25.00 FL
27	1		*TAILLAMP PANEL	Repair	58.90 FL	*- FL
28	1		*END PANEL	Bent	265.40 FL	*265.40 FL
29	1		*END PANEL GARNISH	Mtg Cracked	50.30 FL	*50.30 FL
30	1		*REAR FENDER TRIM BOARD LH	Cracked	182.40 FL	*182.40 FL
31	1		*REAR FENDER SPLASH SHIELD LH	Serviceable	63.20 FL	*- FL
32	1		*SPARE TYRE TOP BOARD	Dented	295.40 FL	*295.40 FL
33	1		*SPARE TYRE PANEL	Repair	895.00 FL	*- FL
34	1		*BONNET	Bent	654.10 FL	*654.10 FL
35	2		*BONNET HINGE	Distorted	85.60 FL	*85.60 FL
36	1		*BONNET LOCK	Distorted	85.40 FL	*85.40 FL
37	4		*BONNET INSULATOR CLIPS	Necessary	14.00 FL	*14.00 FL
38	1		*BONNET LOWER AIR SCOOP	Serviceable	80.20 FL	*- FL
39	1		*FRONT BUMPER	Cracked	632.00 FL	*632.00 FL
40	10		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	2		*FRONT BUMPER BRACKETS	Repair	53.40 FL	*- FL
42	1		*FRONT BUMPER REINFORCEMENT	Bent	369.00 FL	*369.00 FL
43	1		*FRONT BUMPER TOP BEAM	Distorted	246.00 FL	*246.00 FL
44	2		*FRONT BUMPER TOP RETAINERS	Cracked	42.00 FL	*42.00 FL
45	1		*FRONT BUMPER SIDE COVER RH	Cracked	42.00 FL	*42.00 FL
46	1		*FRONT BUMPER CENTER AIR GRILLE	Dented	47.00 FL	*47.00 FL
47	1		*FRONT BUMPER CORNER RETAINER RH	Distorted	21.00 FL	*21.00 FL
48	1		*FRONT BUMPER INNER AMBIENCE SENSOR	Cracked	106.00 FL	*106.00 FL
49	1		*FRONT BUMPER TOP RUBBER SEAL	Necessary	28.00 FL	*28.00 FL
50	1		*FRONT BUMPER CORE	Serviceable	395.00 FL	*- FL
51	2		*HORN	Serviceable	62.00 FL	*- FL
52	1		*HEADLAMPS	O/S Cracked / N/S Serviceable	1,228.00 FL	*614.00 FL
53	2		*HEADLAMP TOP CHROME MOULDINGS	O/S Missing / N/S Cracked	202.00 FL	*202.00 FL
54	1		*HEADLAMP TOP CHROME MOULDING RETAINERS	O/S Cracked / N/S Serviceable	94.00 FL	*47.00 FL
55	1		*SUPPORT PANEL	Bent	602.00 FL	*602.00 FL
56	1		*SUPPORT PANEL TOP GARNISH (8 PCS)	Cracked	29.00 FL	*29.00 FL
57	8		*SUPPORT PANEL TOP GARNISH CLIPS	Necessary	28.00 FL	*28.00 FL
58	1		*SUPPORT PANEL STICKER	Necessary	42.00 FL	*42.00 FL
59	1		*AIR CON CONDENSER	Bent	739.00 FL	*704.40 FL
60	1		*AIR CON CONDENSER SIDE AIR GUIDE RH	Cracked	62.00 FL	*62.00 FL
61	1		*AIR CON CONDENSER LIQUID PIPE	Dented	72.00 FL	*72.00 FL
62	1		*AIR CON CONDENSER DISCHARGE HOSE	Dented	83.00 FL	*83.00 FL
63	1		*RADIATOR	Punctured	1,155.00 FL	*1,100.50 FL
64	1		*RADIATOR LOWER CARRIER	Repair	194.00 FL	*- FL
65	1		*RADIATOR FAN ASSY	Serviceable	1,004.00 FL	*- FL
66	1		*FRONT FENDER RH	Buckled	472.00 FL	*472.00 FL
67	1		*FRONT FENDER SIGNAL LAMP	Mtg Cracked	54.80 FL	*54.80 FL
68	1		*FRONT GRILLE	Cracked	133.00 FL	*133.00 FL
69	1		*FRONT GRILLE TOP RUBBER SEAL	Necessary	38.50 FL	*38.50 FL
70	1		*FRONT GRILLE GARNISH	Cracked	28.70 FL	*28.70 FL
71	1		*FRONT GRILLE EMBLEM	Necessary	27.00 FL	*27.00 FL
72	1		*GRILLE CHROME MOULDING	Cracked	201.00 FL	*201.00 FL
73	1		*FRONT SUPPORT TOP PANEL	Buckled	574.00 FL	*574.00 FL
74	1		*AIR CON SUCTION HOSE	Bent	285.00 FL	*285.00 FL
75	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,518.10 11,871.64
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,094.62 2,365.33

Total Parts (\$\$) 12,423.48 9,506.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /TRANSFER BOOT FITTINGS /ANCILLARY ACCESSORIES	New	80.00	50.00
2	TO CONDUCT REAR ELECTRICAL CHECK ,REPLACE BACK UP SENSOR,REPROGRAM SYSTEM	New	180.00	60.00
3	TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS & TRIMS	New	80.00	0.00
4	TO SUPPLY REAR BODY PANEL JOINT SEALANT	New	100.00	30.00
5	TO CONDUCT WATER TEST LEAK	New	30.00	20.00
6	TO CONDUCT FRON ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
7	TO REMOVE/REFIT AIR CON CONDENSER & REFILL AIR CON GAS	New	120.00	100.00
8	TO REMOVE /REFIT ,RADIATOR SYSTEM ,BLEED ,REFILL COOLANT	New	120.00	50.00
9	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	200.00	120.00
10	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF REAR CHASSIS MEMBER INNER PANEL,BOOT HINGE ,FLOOR PANEL ,REAR N/S FENDER ,FRONT CHASSIS MEMBER ,FRONT INNER PANEL ETC .CNT ,WELD SUPPORT, END PANEL,SPARE TYRE PANEL AND PART REPLACEMENT	New	2,500.00	1,260.00
11	TO RESPRAY AFFECTED AREAS	New	1,900.00	1,600.00
Gross Labour Cost (\$\$)			5,340.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >