

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI20008376/DVF3Q2

**Date:** 02/11/2020

### REFERENCE

|                                                        |                                        |
|--------------------------------------------------------|----------------------------------------|
| Handling Insurer: Tokio Marine Insurance Singapore Ltd | Policy No: MW006382                    |
| <b>Claimant</b>                                        |                                        |
| <b>Vehicle No :</b> SHC2959K                           | <b>Insured Vehicle No :</b> GBD2482J   |
| Date of Loss: 10/08/2020                               | Nature of Claim: TP Claim No: M2003875 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                                                     |                               |
|-----------------------------------------------------|-------------------------------|
| Reg No: <b>SHC2959K</b>                             | Engine No: 2ZR2C11746         |
| Make & Model: TOYOTA PRIUS, 1.5 (A)                 | Chassis No: JTDKB3FU003080199 |
| Reg. Date: 02/05/2019 (Man. Year: 2018)             | Odometer: 175337 km           |
| Colour: Blue                                        |                               |
| Engine Capacity: 1798 cc                            |                               |
| Market Value/New Car Price: N/A                     |                               |
| Sum Insured (\$): <b>Market Value/New Car Price</b> |                               |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |     |                          |     |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification:    | No  | Pre-accident Condition:  |     |

### CONDITION OF TYRES

|                                |                               |
|--------------------------------|-------------------------------|
| Front Tyre Size: 195/65 R15    | Rear Tyre Size: 195/65 R15    |
| Front Left Side: Davanti 5 mm  | Rear Left Side: Davanti 5 mm  |
| Front Right Side: Davanti 5 mm | Rear Right Side: Davanti 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS               | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------|------------------|-----------------|------------------|--------------|
| Parts                        | 14,519.54        | 6,077.90        | 8,441.64         | 58.14        |
| Miscellaneous Items          | 0.00             | 0.00            | 0.00             |              |
| Labour                       | 3,900.00         | 1,770.00        | 2,130.00         | 54.62        |
| Paintwork Labour             | 0.00             | 0.00            | 0.00             |              |
| Towing                       | 0.00             | 0.00            | 0.00             |              |
| <b>Gross Total (\$)</b>      | <b>18,419.54</b> | <b>7,847.90</b> | <b>10,571.64</b> | <b>57.39</b> |
| <b>+ GST 7.00/7.00% (\$)</b> | <b>1,289.37</b>  | <b>549.35</b>   | <b>740.02</b>    | <b>57.39</b> |
| <b>Nett Amount (\$)</b>      | <b>19,708.91</b> | <b>8,397.25</b> | <b>11,311.66</b> | <b>57.39</b> |

### INSPECTION

|                             |                          |                                                                                                                  |
|-----------------------------|--------------------------|------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 13/08/2020               |                                                                                                                  |
| Date Inspected:             | 13/08/2020 Inspected At: | Bifrost Auto Pte Ltd (sin Ming) (HQ)<br>Blk 9 Sector C, #01-42 Sin Ming<br>Industrial Estate<br>Singapore 575644 |
| Estimated Period of Repair: | 5.0 days                 |                                                                                                                  |

**Adjuster:** BRYAN TANI

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 30 Oct 2020)          |
| <b>Parts:</b>        | 144                                                                                                                                                                          | TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SHC2959K)                                                                                                                                    |                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                        |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Reference | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|-----------|--------------|
| 1   | 1   |          | *REAR TRUNK LID COVER                 | Bent / Dented | 1,126.60 FL | -         | *1,126.60 FL |
| 2   | 1   |          | *REAR TRUNK LID LOCK                  | Damaged       | 457.90 FL   | -         | *457.90 FL   |
| 3   | 1   |          | *REAR TRUNK LID COVER BOARD           | Broken        | 216.50 FL   | -         | *216.50 FL   |
| 4   | 1   |          | *BOOT LID TRIMBARD ,CENTRE            | Not Necessary | 159.60 FL   | -         | *- FL        |
| 5   | 1   |          | *BOOT LID TRIMBARD SIDE (LH)          | Not Necessary | 92.50 FL    | -         | *- FL        |
| 6   | 1   |          | *BOOT LID TRIMBARD REAR               | Not Necessary | 124.80 FL   | -         | *- FL        |
| 7   | 1   |          | *REAR TRUNK LID RUBBER                | Deformed      | 365.20 FL   | -         | *365.20 FL   |
| 8   | 1   |          | *REAR TRUNK LID GLASS (BLACK COLOR)   | Shattered     | 969.70 FL   | -         | *969.70 FL   |
| 9   | 1   |          | *BOARD ASSY ,BACK DOOR TRIM           | Not Necessary | 354.40 FL   | -         | *- FL        |
| 10  | 1   |          | *REAR TRUNK LID LOGO (PRIUS)          | Necessary     | 60.80 FL    | -         | *60.80 FL    |
| 11  | 1   |          | *REAR TRUNK LID LOGO (HYBRID)         | Necessary     | 52.40 FL    | -         | *52.40 FL    |
| 12  | 1   |          | *REAR TRUNK LID LOGO (TOYOTA STAR)    | Necessary     | 52.90 FL    | -         | *52.90 FL    |
| 13  | 1   |          | *THIRD BRAKE LIGHT                    | Not Necessary | 394.70 FL   | -         | *- FL        |
| 14  | 1   |          | *REAR TRUNK LID HINGE (LH)            | Not Necessary | 189.50 FL   | -         | *- FL        |
| 15  | 1   |          | *REAR TRUNK LID ABSORBER (LH)         | Not Necessary | 287.50 FL   | -         | *- FL        |
| 16  | 1   |          | *REAR TRUNK LID ABSORBER BRACKET (LH) | Not Necessary | 127.90 FL   | -         | *- FL        |
| 17  | 1   |          | *REAR TRUNK LID STOPPER (LH)          | Not Necessary | 84.80 FL    | -         | *- FL        |
| 18  | 1   |          | *REAR BUMPER                          | Torn          | 458.60 FL   | -         | *458.60 FL   |
| 19  | 1   |          | *REAR BUMPER REINFORCEMENT            | Bent          | 318.80 FL   | -         | *318.80 FL   |
| 20  | 1   |          | *REAR BUMPER LOWER COVER              | Torn          | 552.60 FL   | -         | *552.60 FL   |
| 21  | 1   |          | *REAR BUMPER SIDE RETAINER            | Serviceable   | 112.70 FL   | -         | *- FL        |
| 22  | 1   |          | *REAR BUMPER TOWING COVER             | Dislodged     | 82.70 FL    | -         | *82.70 FL    |
| 23  | 1   |          | *REAR BUMPER CLIPS                    | Necessary     | 22.00 FL    | -         | *22.00 FL    |
| 24  | 1   |          | *REAR BUMPER UPPER STOPPER (LH)       | Not Necessary | 76.40 FL    | -         | *- FL        |
| 25  | 1   |          | *SEAL ,REAR BUMPER SIDE ,LH           | Mtg Cracked   | 148.40 FL   | -         | *148.40 FL   |
| 26  | 1   |          | *REAR BUMPER UNDER SIDE COVER (LH)    | Not Necessary | 232.00 FL   | -         | *- FL        |
| 27  | 1   |          | *ARM SUB-ASSY ,REAR BUMPER ,LH        | Not Necessary | 139.60 FL   | -         | *- FL        |
| 28  | 2   |          | *TAIL LAMP ASSY (UPPER)               | Cracked       | 1,115.80 FL | -         | *1,115.80 FL |
| 29  | 2   |          | *TAIL LAMP ASSY (LOWER)               | Cracked       | 1,096.80 FL | -         | *1,096.80 FL |
| 30  | 1   |          | *TAIL LAMP QUARTER PANEL              | Repair        | 216.00 FL   | -         | *- FL        |
| 31  | 1   |          | *TAIL LAMP SIDE COVER                 | Not Necessary | 256.00 FL   | -         | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                    | Condition        | Repairer's | Reference | Amount     |
|-----|-----|----------|--------------------------------|------------------|------------|-----------|------------|
| 32  | 2   |          | *REAR TAILLAMP GUIDE -WHITE    | Not<br>Necessary | 190.60 FL  | -         | *- FL      |
| 33  | 1   |          | *REAR END PANEL                | Dented           | 602.10 FL  | -         | *602.10 FL |
| 34  | 1   |          | *REAR END PANEL GARNISH        | Mtg Deformed     | 161.80 FL  | -         | *161.80 FL |
| 35  | 1   |          | *REAR WIRING ASSY              | Not<br>Necessary | 582.40 FL  | -         | *- FL      |
| 36  | 1   |          | *REAR SPARE TYRE PANEL         | Not<br>Necessary | 667.70 FL  | -         | *- FL      |
| 37  | 1   |          | *REAR FIBER TOOL BOX TRIM (LH) | Not<br>Necessary | 598.00 FL  | -         | *- FL      |
| 38  | 1   |          | *REAR FIBER TOOL BOX CENTER    | Not<br>Necessary | 186.20 FL  | -         | *- FL      |
| 39  | 1   |          | *SPARE TYRE LOCK NUT           | Not<br>Necessary | 88.40 FL   | -         | *- FL      |
| 40  | 1   |          | *SPARE TYRE LOCK NUT BRACKET   | Not<br>Necessary | 113.50 FL  | -         | *- FL      |
| 41  | 1   |          | *SPARE TYRE SIDE PANEL (LH)    | Not<br>Necessary | 196.50 FL  | -         | *- FL      |
| 42  | 1   |          | *REAR FENDER LH                | Not<br>Necessary | 836.70 FL  | -         | *- FL      |
| 43  | 1   |          | *REAR FENDER SHIELD (LH)       | Not<br>Necessary | 174.20 FL  | -         | *- FL      |
| 44  | 1   |          | *REAR FENDER AIR DUCT          | Not<br>Necessary | 165.10 FL  | -         | *- FL      |
| 45  | 1   |          | *REAR FLOOR PANEL SIDE (LH)    | Not<br>Necessary | 717.60 FL  | -         | *- FL      |
| 46  | 1   |          | *REAR FLOOR UNDER COVER (LH)   | Not<br>Necessary | 846.80 FL  | -         | *- FL      |
| 47  | 1   |          | *REAR CROSSMEMBER UNDER COVER  | Not<br>Necessary | 891.10 FL  | -         | *- FL      |
| 48  | 1   |          | *REVERSE CAMERA ASSY           | Not<br>Necessary | 380.00 FS  | -         | *- FS      |
| 49  | 1   |          | *REAR TRUNK LOWER W/S MOULDING | Not<br>Necessary | 180.00 FS  | -         | *- FS      |
| 50  | 1   |          | *REAR LOWER W/S SEALANT        | Not<br>Necessary | 46.00 FS   | -         | *- FS      |
| 51  | 1   |          | *REAR WINDSCREEN MOULDING      | Not<br>Necessary | 160.00 FS  | -         | *- FS      |
| 52  | 1   |          | *REAR WINDSCREEN SEALANT       | Necessary        | 46.00 FS   | -         | *46.00 FS  |
| 53  | 1   |          | *REAR BUMPER REVERSE SENSOR    | Damaged          | 135.70 FS  | -         | *135.70 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 17,912.50 8,043.30**  
**- List Item Discount on L Items 20.00/25.00% (\$\$) 3,392.96 1,965.40**

**Total Parts (\$\$) 14,519.54 6,077.90**

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                            |          |                 |                 |
| 1                               | PANEL BEATING                              | New      | 1,200.00        | 800.00          |
| 2                               | SPRAY PAINTING CHARGE                      | New      | 1,000.00        | 700.00          |
| 3                               | WIRING CHARGE                              | New      | 140.00          | 30.00           |
| 4                               | TUFF KOTE                                  | New      | 140.00          | 40.00           |
| 5                               | TOWING CHARGE                              | New      | 80.00           | 0.00            |
| 6                               | REMOVE/REFIX CUSHION & UPHOLSTERY REAR     | New      | 150.00          | 80.00           |
| 7                               | REMOVE/REFIX REAR WINDSCREEN GLASS         | New      | 120.00          | 80.00           |
| 8                               | REMOVE/REFIX REVERSE SENSOR                | New      | 120.00          | 40.00           |
| 9                               | RE-SET REAR ABS SYSTEM                     | New      | 400.00          | 0.00            |
| 10                              | DIAGNOSTIC & RESETTING TO ERASE FAULT CODE | New      | 550.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                            |          | <b>3,900.00</b> | <b>1,770.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >