

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2020 Sendback Est	13 Aug 2020 11:59 S\$6,131.91	13 Aug 2020 17:02 Edit Adj Rpt	S\$3,850.27 Edit Estimates	S\$3,850.27 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: THINK ONE LEASING PTE LTD , Co. Reg. No.: 201115609M									
Main Claimant: CTPL									
Vehicle Reg. No.:	SHC1323B	Date of Loss:	11/08/2020 00:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2003931	Policy/Cover Note No.:	ML000183 (TP, Fire & Theft) Coverage: 01/04/2020 - 31/03/2021						
Vehicle Reg. No. (Insured):	YP7907H	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/08/2020]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC1323B (M2003931)
[YP7907H]
TP
CTPL
Aug 11 2020 12:00AM
[THINK ONE LEASING PTE LTD]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		
1	13/08/20 11:59	Repairer Estimates	 Load HTM	Thumbnail Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	14/08/20 16:16	Adjuster Immediate Advice	 Load HTM	Thumbnail Print
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	24/08/20 11:06	Odometer Reading	 Load JPG	Thumbnail Print
2	24/08/20 11:06	Chassis Number	 Load JPG	Thumbnail Print
3	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
4	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
5	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
6	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
7	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
8	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
9	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
10	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
11	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
12	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
13	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
14	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
15	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
16	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
17	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
18	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
19	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
20	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
21	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
22	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
23	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
24	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
25	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
26	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
27	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
28	24/08/20 11:06	General View	 Load JPG	Thumbnail Print
29	24/08/20 11:06	After Repair Photo	 Load JPG	Thumbnail Print
30	24/08/20 11:06	After Repair Photo	 Load JPG	Thumbnail Print
31	24/08/20 11:06	After Repair Photo	 Load JPG	Thumbnail Print
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		
1	24/08/20 11:02	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	Thumbnail Print
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		
				Thumbnail Print

Assessment Reports				1 per page ▾	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	13/08/20 12:00	E-filed GIA report		Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	14/08/20 20:16	TP - SHC1232B - Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI20008379/T1SF3S2**Date:** 25/08/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000183	
Claimant Vehicle No :	SHC1323B	Insured Vehicle No :	YP7907H	
Date of Loss:	11/08/2020	Nature of Claim:	TP	Claim No: M2003931

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1323B	Engine No:	2ZRS054121
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU103560560
Reg. Date:	19/07/2017 (Man. Year: 2017)	Odometer:	415538 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,900.91	3,189.27	1,711.64	34.92
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,220.00	650.00	570.00	46.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,131.91	3,850.27	2,281.64	37.21
+ GST 7.00/7.00% (S\$)	429.23	269.52	159.71	37.21
Nett Amount (S\$)	6,561.14	4,119.79	2,441.35	37.21

INSPECTION

Date of Assignment:	13/08/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/08/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2020)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1323B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Deformed	499.90 FL	-	*499.90 FL
2	1		*FRT BUMPER REINFORCEMENT	Not Necessary	696.40 FL	-	*- FL
3	1		*FRT BUMPER SIDE BRACKET RH	Not Necessary	82.30 FL	-	*- FL
4	1		*FRT BUMPER SIDE BRACKET LH	Not Necessary	82.30 FL	-	*- FL
5	1		*FRT BUMPER CENTRE GRILLE	Not Necessary	318.80 FL	-	*- FL
6	1		*RADIATOR GRILLE	Cracked	88.00 FL	-	*88.00 FL
7	1		*FRT GRILLE EMBLEM	Cracked	43.80 FL	-	*43.80 FL
8	1		*FRT BUMPER TOW COVER	Not Necessary	28.38 FL	-	*- FL
9	1		*FRT NUMBER EXT. GARNISH	Cracked	99.00 FL	-	*99.00 FL
10	1		*FRT RUNNING DAYLIGHT RH	Not Necessary	920.00 FL	-	*- FL
11	1		*HEADLAMP ASSY LH	Cracked	3,455.00 FL	-	*3,455.00 FL
12	2		*FRT BUMPER SIDE RETAINER RH/LH	Not Necessary	154.00 FL	-	*- FL
13	1		*FRT NUMBER PLATE	Bent	50.00 F	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,517.88	4,235.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,616.97	1,046.43
Total Parts (\$)	4,900.91	3,189.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	640.00	320.00
2	SPRAYPAINT	New	460.00	300.00
3	CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,220.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >