

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20008380/UQF3E2

Date: 29/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1700010091
Claimant Vehicle No : GBB6896H	Insured Vehicle No : SLP2348H
Date of Loss: 30/07/2020	Nature of Claim: TP Claim No: 4879735774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB6896H		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30234304K
Reg. Date:	11/12/2009 (Man. Year: 2009)	Chassis No:	JN1SC2F24Z0801244
Colour:	White	Odometer:	508966 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	GREEN-MAX 6 mm	Rear Left Side:	West Lake 6/6 mm
Front Right Side:	GREEN-MAX 6 mm	Rear Right Side:	West Lake 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,165.24	7,507.91	5,657.33	42.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	2,510.00	860.00	25.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,535.24	10,017.91	6,517.33	39.41
Approved Total (Overridden) (\$\$)		8,000.00		
(\$\$)	16,535.24	8,000.00	8,535.24	51.62
+ GST 7.00/7.00% (\$\$)	1,157.47	560.00	597.47	51.62
Nett Amount (\$\$)	17,692.71	8,560.00	9,132.71	51.62

INSPECTION

Date of Assignment:	13/08/2020	
Date Inspected:	16/09/2020	Inspected At:
		SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	1,583.60 FL	*1,580.90 FL
2	1		*FRONT PANEL EMBLEM CABSTAR	Necessary	71.20 FL	*36.10 FL
3	1		*FRONT WIPER GARNISH	Not Necessary	494.60 FL	*- FL
4	1		*FRONT GRILLE	Cracked	578.60 FL	*461.90 FL
5	1		*FRONT GRILLE LOGO EMBLEM	Necessary	55.10 FL	*55.10 FL
6	2		*HEADLAMP L/R	Cracked	1,364.00 FL	*1,364.00 FL
7	2		*HEADLAMP APRON GARNISH R/L	Not Necessary	150.80 FL	*- FL
8	1		*FRONT BUMPER	Distorted	993.40 FL	*903.60 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	702.60 FL	*481.00 FL
10	1		*FRONT MIRROR BRACKET LH	Not Necessary	191.10 FL	*- FL
11	1		*FRONT MIRROR BRACKET CAP COVER LH	Not Necessary	22.90 FL	*- FL
12	1		*FRONT MIRROR BRACKET GARNISH LH	Not Necessary	111.30 FL	*- FL
13	1		*FRONT ROUND MIRROR LH	Not Necessary	105.30 FL	*- FL
14	2		*FRONT WIPER ARM	Not Necessary	206.20 FL	*- FL
15	1		*FRONT MIRROR BRACKET RH	Not Necessary	191.90 FL	*- FL
16	1		*FRONT MIRROR BRACKET CAP COVER RH	Not Necessary	22.90 FL	*- FL
17	1		*FRONT MIRROR BRACKET GARNISH RH	Not Necessary	111.30 FL	*- FL
18	1		*FRONT MIRROR BRACKET INNER COVER RH	Not Necessary	22.90 FL	*- FL
19	1		*FRONT WINDSCREEN LOWER MOULDING	Necessary	24.70 FL	*24.70 FL
20	2		*FRONT WINDSCREEN SIDE MOULDING L/R	Necessary	134.40 FL	*134.40 FL
21	1		*FRONT WINDSCREEN UPPER MOULDING	Necessary	93.50 FL	*93.50 FL
22	1		*TAILGATE LOWER MEMBER	Bent	645.50 FL	*645.50 FL
23	1		*TAILGATE STOPPER BRACKET	N/S Twisted	210.00 FL	*105.00 FL
24	1		*REAR NUMBER PLATE LAMP	Not Necessary	71.30 FL	*- FL
25	1		*REAR NUMBER PLATE BRACKET	Bent	112.00 FL	*112.00 FL
26	2		*TAILLAMP PANEL R/L	Not Necessary	336.80 FL	*- FL
27	1		*TAILLAMP R/L	N/S Cracked	439.60 FL	*219.80 FL
28	1		*REAR NUMBER PLATE LAMP	Repeated	71.30 FL	*- FL
29	1		*TAILGATE RUBBER STOPPER L/R (4PCS)	N/S Torn	204.80 FL	*102.40 FL
30	1		*TAILGATE R/L	N/S Dented / Bent / O/S Repair	2,400.00 FS	*900.00 FS
31	2		*TAILGATE LOCK R/L	Not Necessary	500.00 FS	*- FS
32	2		*TAILGATE LOCK CATCH UPPER R/L	Not Necessary	150.00 FS	*- FS
33	2		*TAILGATE LOCK CATCH LOWER R/L	Not Necessary	150.00 FS	*- FS
34	1		*TAILGATE LOWER MEMBER STAINLESS STEEL PANEL	Bent	350.00 FS	*300.00 FS
35	1		*SET REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
36	1		*REAR SAFETY BEAM	Bent	650.00 FS	*300.00 FS
37	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS
38	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
39	1		*FRONT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*FRONT WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
41	1		*SET FRONT GRILLE CLIP	Not Necessary	24.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,097.60 8,139.90
- List Item Discount on L Items 10.00/10.00% (\$\$) 932.36 631.99

Total Parts (\$\$) 13,165.24 7,507.91

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY PAINTING ON AFFECTED AREA	New	1,500.00	1,100.00
2	TO PROVIDE LABOUR TO REPAIR & REPLACE DAMAGED PARTS	New	1,500.00	1,200.00
3	TO APPLY ANTI-RUST CHEMICAL ON AFFECTED AREA	New	100.00	30.00
4	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING	New	50.00	30.00
5	TO REMOVE, RENEW REVERSE SENSOR	New	80.00	50.00
6	TO REMOVE, REFIX FRONT WINDSCREEN GLASS	New	140.00	100.00
Gross Labour Cost (S\$)			3,370.00	2,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >