Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008385/T1TF3Q2

Date: 30/10/2020

REFERENCE

China Taiping Insurance Policy No: Handling Insurer:

(Singapore) Pte. Ltd.

DMCVSNA00045422002

Claimant Vehicle No:

Insured Vehicle No:

GBH5668A

Date of Loss:

Reg. Date:

SLE710R 12/08/2020

Nature of

Claim:

ΤP

Claim

Odometer:

SNM20D202842/C02/THAMYL

20861 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE710R

Make & Model: INFINITI Q50, 2.0 T Base EU6 (A)

Engine No: KR20019412A 26/03/2019 (Man. Year: 2018) Chassis No: 3PCMAAJ55Z0550836

Colour: White

Engine Capacity: 1997 cc

Market Value/New Car

Sum Insured (S\$):

N/A

Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R17 235/50 R17 Rear Tyre Size: Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,283.15	5,723.01	560.14	8.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	3,980.00	1,700.00	29.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,963.15	9,703.01	2,260.14	18.89
+ GST 7.00/7.00% (S\$)	837.42	679.21	158.21	18.89
Nett Amount (S\$)	12,800.57	10,382.22	2,418.35	18.89

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 05/10/2020 Inspected At: Wearnes automotive Pte Ltd (HQ)

45 LENG KEE ROAD Singapore 159103

Estimated Period of Repair: 4.0 days

Manager: DENISE TAY KWEE CHENG MOHD TAUFIKH BIN HAMID Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference			
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2020)	
Parts:	143	INFINITI Q50 2.0 T Base EU6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLE710R)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SET FR	Deformed	831.90 FS	*748.71 FS
2	1		*SEAL ASSY -HOOD	Necessary	41.00 FS	*36.90 FS
3	1		*LAMP ASSY LH	Cut	3,759.30 FS	*3,383.82 FS
4	1		*HOOD	Bent	973.70 FS	*876.33 FS
5	1		*GRILLE -RADIATOR	Cracked	677.25 FS	*677.25 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	6,283.15	5,723.01

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE ,FRT BUMPER ,RAD GRILLE,BONNET ,HEADLAMP LH ETC	New	2,700.00	1,800.00
2	TO SPRAYPAINT ON FRT BUMPER ,BONNET ,ETC	New	2,400.00	1,600.00
3	TO FOCUS HEADLAMP	New	145.00	145.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	435.00	435.00
	Gross Lal	oour Cost (S\$)	5,680.00	3,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >