

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG20008387/R1TF3E2

Date: 14/09/2020

REFERENCE

Insured/Claimant:	TEO LILY	Policy No:	A29123955AV2
Date of Loss:	11/08/2020	Nature of Claim:	OD
		Claim No:	627228

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK8631P		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A)	Engine No:	CZDA16604
Reg. Date:	26/04/2019 (Man. Year: 2019)	Chassis No:	WVGZZZ1TZKW044188
Colour:	Blue	Odometer:	29320 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$107,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,240.12	11,244.99	1,995.13	15.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,840.00	6,340.00	2,500.00	28.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,080.12	17,584.99	4,495.13	20.36
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	20,580.12	16,084.99	4,495.13	21.84
+ GST 7.00/7.00% (S\$)	1,440.61	1,125.95	314.66	21.84
Nett Amount (S\$)	22,020.73	17,210.94	4,809.79	21.84

INSPECTION

Date of Assignment:	13/08/2020	
Date Inspected:	13/08/2020	Inspected At:
		Volkswagen Centre Singapore (HQ) NO 17 TUAS AVE 9 SINGAPORE 639197

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2020)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 1.4 TSI CL 5T13NZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8631P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD FRT BONNET	Bent	1,853.60 FS	*1,853.60 FS
2	1		*DECKLID WEATHERSTRIP BONNET SEAL RH	Necessary	16.14 FS	*16.14 FS
3	1		*FLAP HINGE LH	Bent	196.92 FS	*196.92 FS
4	1		*FLAP HINGE RH	Bent	196.92 FS	*196.92 FS
5	1		*HOOD LATCH BONNET LOCK	Serviceable	230.03 FS	*- FS
6	1		*COVER FOR BUMPER PRIMED	Deformed	1,145.18 FS	*1,145.18 FS
7	1		*SPOILER SATIN BLACK	Deformed	237.02 FS	*237.02 FS
8	1		*SUPPORT PART BUMPER INNER BRACKET LH	Serviceable	40.60 FS	*- FS
9	1		*SUPPORT PART BUMPER INNER BRACKET RH	Missing	40.60 FS	*40.60 FS
10	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Serviceable	36.87 FS	*- FS
11	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Cracked	36.87 FS	*36.87 FS
12	1		*IMPACT BEAM REINFORCEMENT	Bent	549.86 FS	*549.86 FS
13	2		*RIVETTED CAP NUT	Necessary	5.44 FS	*5.44 FS
14	1		*FOAM INSERT	Cracked	50.33 FS	*50.33 FS
15	1		*PRESSURE SENSOR (PRESSURE SENSOR) FOAM	Serviceable	162.86 FS	*- FS
16	1		*CRASH SENSOR FOR AIRBAG	Serviceable	221.52 FS	*- FS
17	1		*RADIATOR GRILLE WITH SATI	Cracked	380.59 FS	*380.59 FS
18	1		*VW SIGN BLACK / BRIGHT CHRO	Missing	163.04 FS	*163.04 FS
19	1		*COVER PART FOR BUMPER SAT FOG LAMP GRILLE RH	Missing	68.81 FS	*68.81 FS
20	1		*COVER PART FOR BUMPER SAT FOG LAMP GRILLE LOWER TRIM RH	Scratched	26.02 FS	*26.02 FS
21	1		*LED HEADLIGHT H/LAMP RH	Cracked	1,638.79 FS	*1,638.79 FS
22	1		*POWER MODULE FOR MAIN LIG	Serviceable	361.38 FS	*- FS
23	1		*CONTROL UNIT FOR LIGHT CO RH	Serviceable	276.28 FS	*- FS
24	1		*LED HEADLIGHT H/LAMP LH	Missing	1,638.79 FS	*1,638.79 FS
25	1		*POWER MODULE FOR MAIN LIG	Missing	361.38 FS	*361.38 FS
26	1		*CONTROL UNIT FOR LIGHT CO	Missing	276.28 FS	*276.28 FS
27	1		*HEX SOCKET HEAD BOLT (3PCS)	Necessary	5.32 FS	*5.32 FS
28	1		*OVAL HEXAGON SOCKET HEAD (2PCS)	Necessary	2.61 FS	*2.61 FS
29	1		*OVAL SOCKET HEAD BOLT WIT (6PCS)	Necessary	6.64 FS	*6.64 FS
30	1		*LOCK CARRIER WITH MOUNTIN	Cut	972.05 FS	*972.05 FS
31	1		*GUIDE BUMPER CENTRE BRACKET	Cracked	53.93 FS	*53.93 FS
32	1		*CROSS SUPPORT H/LAMP TOP PANEL LH	Serviceable	28.51 FS	*- FS
33	1		*CROSS SUPPORT H/LAMP TOP PANEL RH	Serviceable	28.51 FS	*- FS
34	1		*AIR DUCT AIR GUIDE RH	Serviceable	23.48 FS	*- FS
35	1		*AIR DUCT AIR GUIDE LH	Deformed	23.48 FS	*23.48 FS
36	2		*COOLANT CONCENTRATE	Necessary	76.48 FS	*76.48 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*FENDER LH	Bent	585.09 FS	*585.09 FS
38	1		*FENDER RH	Repair	585.09 FS	*- FS
39	1		*WHEEL HOUS FENDER LINER RH	Cut	132.71 FS	*132.71 FS
40	1		*SPOILER	Necessary	25.04 FS	*25.04 FS
41	1		*EXPANDING NUT (4PCS)	Necessary	5.98 FS	*5.98 FS
42	4		*HEX SOCKET OVAL HEAD COIL	Necessary	2.16 FS	*2.16 FS
43	1		*RIVETTED CAP NUT (2PCS)	Necessary	4.01 FS	*4.01 FS
44	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
45	1		*COOLING AIR GRILL SATIN B BUMPER CENTRE LOWER GRILLE	Scratched	155.05 FS	*155.05 FS
46	1		*HALOGEN FOG LIGHTS WITH S FOG LAMP RH	Cracked	231.86 FS	*231.86 FS
					Total Parts (S\$)	13,240.12 11,244.99

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	A/C GAS	New	60.00	60.00
4	LEAKED CHECK, VACUUM & REGAS	New	325.00	325.00
5	TOWING ASSISTANCE - ALLIANZ	New	195.00	195.00
6	LABOUR	New	3,900.00	2,600.00
7	SPRAY PAINT	New	3,600.00	2,400.00
Gross Labour Cost (S\$)			8,840.00	6,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >