

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008388/KES3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800072446

Claimant
Vehicle No : SLB6284E **Insured Vehicle No :** SMA7915E

Date of Loss: 08/08/2020 Nature of Claim: TP Claim No: 7756393972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|---------------|
| Reg No: | SLB6284E | | |
| Make & Model: | TOYOTA SIENTA, 1.5 (A) | Engine No: | 2NR8584560 |
| Reg. Date: | 07/09/2016 (Man. Year: 2015) | Chassis No: | NSP1707023039 |
| Colour: | Metallic Silver | Odometer: | 69848 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 185/60 R15 | Rear Tyre Size: | 185/60 R15 |
| Front Left Side: | Michelin 9 mm | Rear Left Side: | Michelin 9 mm |
| Front Right Side: | Michelin 9 mm | Rear Right Side: | Michelin 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 1,310.85 | 1,310.85 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,210.00 | 930.00 | 280.00 | 23.14 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 2,520.85 | 2,240.85 | 280.00 | 11.11 |
| + GST 7.00/7.00% (\$\$) | 176.46 | 156.86 | 19.60 | 11.11 |
| Nett Amount (\$\$) | 2,697.31 | 2,397.71 | 299.60 | 11.11 |
| + Car Rental (4.0 x S\$100.00/day) (\$\$) | | 400.00 | | |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 2,799.71 | | |

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 14/08/2020 Inspected At:

Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|--------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Bent | 1,131.90 FL | *1,131.90 FL |
| 2 | 1 | | *TAILGATE CENTRE LOGO | Necessary | 72.20 FL | *72.20 FL |
| 3 | 1 | | *NUMBER PLATE LAMP GARNISH | Warped | 207.90 FL | *207.90 FL |
| 4 | 2 | | *REAR WINDSCREEN MOULDING (1 SET) | Necessary | 105.80 FL | *105.80 FL |
| 5 | 1 | | *REAR BUMPER CENTRE GARNISH | Dented / Cut | 190.00 FL | *190.00 FL |
| 6 | 2 | | *WINDSCREEN SEALANT | Necessary | 30.00 FS | *30.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 1,737.80 | 1,737.80 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 426.95 | 426.95 |
| Total Parts (\$) | 1,310.85 | 1,310.85 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE & REFIT REAR WINDSCREEN | New | 120.00 | 120.00 |
| 2 | TO DISMANTLE AND INSTALL TAILGATE AND TRANSFER WIRING HARNESS ,LAMP AND INNER LOCK | New | 90.00 | 60.00 |
| 3 | TO DISMANTLE AND INSTALL DAMAGE PARTS ,TO KNOCK ,ALIGN AND REPAIR REAR AFFECTED AREA AND TO REFIT LISTED PARTS BACK SAME | New | 500.00 | 350.00 |
| 4 | TO SPRAY TAILGATE AND REAR BUMPER | New | 500.00 | 400.00 |
| Gross Labour Cost (\$\$) | | | 1,210.00 | 930.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >