

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20008389/DVF3E2
Date: 30/12/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29145877		
Claimant Vehicle No :	SHD6528P	Insured Vehicle No :	YN6897U		
Date of Loss:	08/08/2020	Nature of Claim:	TP	Claim No:	627407

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6528P	Engine No:	2ZR2G04014
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU403090315
Reg. Date:	13/12/2019 (Man. Year: 2019)	Odometer:	69704 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,692.12	8,357.14	14,334.98	63.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	1,430.00	2,620.00	64.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,742.12	9,787.14	16,954.98	63.40
+ GST 7.00/7.00% (S\$)	1,871.95	685.10	1,186.85	63.40
Nett Amount (S\$)	28,614.07	10,472.24	18,141.83	63.40

INSPECTION

Date of Assignment:	13/08/2020		
Date Inspected:	13/08/2020	Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6528P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Bent/Cut	705.61 FL	*705.61 FL
2	1		*LAMP ASSY,FOG,LH	Not Necessary	1,298.58 FL	*- FL
3	1		*FRONT BUMPER CLIPS	Necessary	31.05 FL	*31.05 FL
4	1		*FRONT BUMPER SIDE RETAINER	Serviceable	108.69 FL	*- FL
5	1		*FRONT LOWER CROSSMEMBER	Not Necessary	504.89 FL	*- FL
6	1		*FRONT BUMPER TOP GARNISH	Not Necessary	318.15 FL	*- FL
7	1		*ABSORBER,FRONT BUMPER,LOWER	Not Necessary	180.25 FL	*- FL
8	1		*UNIT ASSY,HEADLAMP (LH) LED	Mounting Cracked	4,876.73 FL	*3,455.00 FL
9	1		*HEAD LAMP PANEL (LH)	Not Necessary	338.90 FL	*- FL
10	1		*TOP PANEL SIDE	Not Necessary	205.94 FL	*- FL
11	1		*FENDER SUB-ASSY,FRONT LH	Dented	1,334.29 FL	*1,334.29 FL
12	1		*FRONT FENDER SHIELD	Bent/Deformed	280.18 FL	*280.18 FL
13	1		*FRONT FENDER SHIELD CLIP	Necessary	21.03 FL	*21.03 FL
14	1		*FRONT FENDER HYBRID EMBLEM,LH	Necessary	122.09 FL	*122.09 FL
15	1		*FRONT WHEEL RIM	Not Necessary	2,216.83 FL	*- FL
16	1		*FRONT WHEEL HUB CAP	Cut	248.14 FL	*248.14 FL
17	1		*FRONT WHEEL HUB BEARING	Damaged	790.36 FL	*790.36 FL
18	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	891.93 FL	*891.93 FL
19	1		*FRONT SHOCK ABSORBER (LH)	Distorted	562.06 FL	*562.06 FL
20	1		*ABSORBER TOP MOUNTING	Not Necessary	276.94 FL	*- FL
21	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	2,489.89 FL	*- FL
22	1		*RACK & PINION ASSY	Not Necessary	2,288.46 FL	*- FL
23	1		*BAR,STABILIZER	Not Necessary	497.41 FL	*- FL
24	1		*LINK ASSY,FRONT STABILIZER LH	Not Necessary	277.78 FL	*- FL
25	1		*KNUCKLE,STEERING LH	Distorted	819.80 FL	*819.80 FL
26	1		*JOINT ASSY,LOWER BALL,FRONT (LH)	Bent	282.27 FL	*282.27 FL
27	1		*DISC,FRONT	Not Necessary	593.78 FL	*- FL
28	1		*END SUB-ASSY,TIE ROD,LH	Distorted	224.85 FL	*224.85 FL
29	1		*SENSOR,SPEED,FRONT LH	Not Necessary	630.23 FL	*- FL
30	1		*FRONT CHASSIS MEMBER (LH)	Not Necessary	2,838.24 FL	*- FL
31	1		*MIRROR ASSY,OUTER REAR VIEW,LH	Broken	1,728.70 FL	*1,374.20 FL
32	1		*FRONT TYRE (RH)	Not Necessary	304.88 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	28,288.93	11,142.86
					- List Item Discount on L Items 20.00/25.00% (S\$)	5,596.81	2,785.72
					Total Parts (S\$)	22,692.12	8,357.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING CHARGE	New	1,000.00	500.00
3	WIRING CHARGE	New	140.00	0.00
4	TUFF KOTE	New	140.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	60.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	FRONT CHASSIS ALIGNMENT CHARGE	New	220.00	0.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
			Gross Labour Cost (\$\$)	4,050.00
				1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >