

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008392/GES3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900257782

Claimant
Vehicle No : SMK6540G **Insured Vehicle No :** SMR3913Y

Date of Loss: 11/08/2020 Nature of Claim: TP Claim No: 6303099015SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6540G		
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Engine No:	2NRX449699
Reg. Date:	18/04/2019 (Man. Year: 2019)	Chassis No:	MHFZ28H3700063485
Colour:	Brown	Odometer:	11746 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,211.15	1,083.05	128.10	10.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	830.00	230.00	21.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,271.15	1,913.05	358.10	15.77
+ GST 7.00/7.00% (\$\$)	158.98	133.91	25.07	15.77
Nett Amount (\$\$)	2,430.13	2,046.96	383.17	15.77
+ Car Rental (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,648.96		

INSPECTION

Date of Assignment: 13/08/2020

Date Inspected: 13/08/2020 Inspected At:

Vin's Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive, #03-03, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILLAMP	Cracked	347.00 FL	*347.00 FL
2	1		*REAR LH TAILLAMP LOWER BRACKET	Deformed	92.33 FL	*92.33 FL
3	1		*REAR BUMPER	Deformed	278.00 FL	*278.00 FL
4	1		*REAR BUMPER LH PAD	Cut	122.80 FL	*122.80 FL
5	1		*REAR BUMPER CENTRE PAD	Deformed	180.70 FL	*180.70 FL
6	1		*REAR BUMPER LH REFLECTOR	Not Necessary	56.90 FL	*- FL
7	1		*REAR BUMPER LH RETAINER	Missing	89.90 FL	*89.90 FL
8	1		*REAR LH FENDER MUD FLAP	Not Necessary	73.90 FL	*- FL
9	1		*SET REAR BUMPER SENSOR	Not Working	280.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,521.53	1,360.73
- List Item Discount on L Items 25.00/25.00% (\$\$)	310.38	277.68
Total Parts (\$\$)	1,211.15	1,083.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR DAMAGES	New	480.00	350.00
2	TO SPRAY PAINTING	New	580.00	480.00
Gross Labour Cost (\$)			1,060.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >