



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : S3760CDMake & Model : HONDA ODYSSEY 2.4 EXV-SYear of Manufacture : 2015Chassis No. : JHMRC1890FC203253Ins Company : AIG VS CHINA TAIPINGEngine No. : K24W71011642Excess : -Policy No. : -Date of Accident : 12.08.2020Time of Accident : 08:30

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 18,609.70Plus/Less 20% \$ 3,721.94Total of Cost / List \$ 14,887.76(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 1,833.00**Total Parts Cost (Appendix A)** \$ 16,720.76**Labour (Appendix B)** \$ 3,830.00**Total Repair Cost** \$ 20,550.76

Contact No

Spark Car Care Service Reception

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 - William Wang

WilliamWangKS@sparkcarcare.com

63837362 - Andrew Goh

AndrewCorneliusGoh@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qian - 82880282Company : LKKSurvey conducted on : 14/8/2020 at _____**Remarks By Surveyor**part by part / before part photos

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 7 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : S3760CD Case Owner : 0

Make & Model : HONDA ODYSSEY 2.4 EXi Year Manufacture : 2015

Chassis No : JHMRC1890FC203253 Engine No : K24W71011642

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing <i>X MV</i>	1				\$ 45 00	
2	Rear bumper <i>/ RL</i>	1		\$ 598 30			
3	Rear bumper spoiler LH <i>X SVC</i>	1		\$ 121 80			
4	Rear bumper spoiler RH <i>X SVC</i>	1		\$ 121 80			
5	Rear bumper reflector LH <i>X</i>	1		\$ 45 00			
6	Rear bumper reflector RH <i>X</i>	1		\$ 45 00			
7	Rear bumper retainer LH <i>X SVC</i>	1		\$ 21 00			
8	Rear bumper retainer RH <i>X SVC</i>	1		\$ 21 00			
9	Rear bumper clips <i>/ ABC</i>	1		\$ 39 00			
10	Reverse sensor set <i>X SVC</i>	1				\$ 380 00	
11	Smart buzzer assy <i>X SVC</i>	1		\$ 85 00			
12	Rear antenna assy <i>X SVC</i>	1		\$ 85 10			
13	Rear end panel <i>X Repair</i>	1		\$ 451 80			
14	Rear end panel inner garnish <i>X SVC</i>	1		\$ 105 00			
15	Taillamp LH <i>X SVC</i>	1		\$ 821 50			
16	Taillamp RH <i>X SVC</i>	1		\$ 821 50			
17	Tailgate <i>/ brace</i>	1		\$ 1 193 70			
18	Tailgate outer garnish <i>/ CAA</i>	1		\$ 246 70			
19	Tailgate outer chrome moulding <i>/ CAA</i>	1		\$ 190 60			
20	Tailgate lamp assy LH <i>X SVC</i>	1		\$ 378 60			
21	Tailgate lamp assy RH <i>/ SCR</i>	1		\$ 378 60			
22	Tailgate lock assy <i>X NV</i>	1		\$ 189 00			
23	Tailgate opener switch assy <i>/ CAA</i>	1		\$ 175 50			
24	Tailgate weatherstrip <i>/ CAA</i>	1		\$ 120 90			
25	Tailgate inner lower garnish <i>X SVC</i>	1		\$ 242 20			
26	Tailgate inner upper garnish <i>X SVC</i>	1		\$ 50 70			
27	Tailgate inner side garnish LH <i>X SVC</i>	1		\$ 47 90			
28	Tailgate inner side garnish RH <i>X SVC</i>	1		\$ 47 90			
29	Rear windscreen glass <i>/ GM</i>	1		\$ 11 458 90		1153.9	
30	Rear windscreen glass side moulding <i>/ MC2</i>	1		\$ 62 60			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : S3760CD Case Owner : 0

Make & Model : HONDA ODYSSEY 2.4 EXV Year Manufacture : 2015

Chassis No : JHMRC1890FC203253 Engine No : K24W71011642

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Rear windscreen glass upper dam <i>✓</i>	1		\$ 31.20			
32	Rear windscreen glass lower dam <i>✓</i>	1		\$ 31.20			
33	Rear windscreen glass dam rubber A <i>✓</i>	1	NN	TBA			
34	Rear windscreen glass pivot cap <i>✓</i> NN	1		TBA			
35	Rear windscreen sealant <i>✓</i>	1				\$ 40.00	
36	Rear windscreen solar film <i>✓</i>	1				\$ 280.00	
37	Rear wiper arm assy <i>✓</i>	1		\$ 50.10			
38	Rear wiper blade <i>✓</i>	1		\$ 48.00			
39	Rear wiper motor assy <i>✓</i> NN	1		\$ 287.60			
40	BlackVue camera set <i>✓</i>	1				\$1,088.00	528
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **S3760CD** Case Owner : **0**
 Make & Model : **ONDA ODYSSEY 2.4 EXV-S** Year of Manufacture : **2015**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	180
2	To remove/replace rear windscreen to facilitate repairs.	\$120.00	✓
3	To transfer tailgate parts and fittings to new tailgate.	\$180.00	80
4	Labour charges to repair and panel beat the LH rear fender, RH rear fender, rear floor panel, cutting/welding and replacing damaged parts. 240	\$1,440.00	1480 720
5	To check wiring functions.	\$40.00	20
6	To remove/replace reverse sensor set.	\$120.00	80
7	To putty, apply primer & spray-paint the rear bumper, tailgate, LH rear fender, RH rear fender, rear end panel, rear floor panel and affected areas. 250	\$1,500.00	750 1000
8	To apply rust-proofing on repaired/replaced panels.	\$150.00	50
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.