

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **S3760CD** Case Owner : **0**
 Make & Model : **ONDA ODYSSEY 2.4 EXV-S** Year of Manufacture : **2015**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$280.00	180
2	To remove/replace rear windscreen to facilitate repairs.	\$120.00	✓
3	To transfer tailgate parts and fittings to new tailgate.	\$180.00	80
4	Labour charges to repair and panel beat the LH rear fender, RH rear fender, rear floor panel, cutting/welding and replacing damaged parts. 240	\$1,440.00	1480 720
5	To check wiring functions.	\$40.00	20
6	To remove/replace reverse sensor set.	\$120.00	80
7	To putty, apply primer & spray-paint the rear bumper, tailgate, LH rear fender, RH rear fender, rear end panel, rear floor panel and affected areas. 250	\$1,500.00	750 1000
8	To apply rust-proofing on repaired/replaced panels.	\$150.00	50
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

20,691.40#